

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004591/ETY3M4**Date:** 03/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00098402104		
Claimant Vehicle No :	SMX7244L	Insured Vehicle No :	GBD2765T		
Date of Loss:	12/05/2022	Nature of Claim:	TP	Claim No:	SNM22D203310/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX7244L		
Make & Model:	VOLKSWAGEN TIGUAN, 1.4 TSI (A)	Engine No:	CZDA84901
Reg. Date:	27/01/2021 (Man. Year: 2019)	Chassis No:	WVGZZZ5NZLW849534
Colour:	Silver	Odometer:	18940 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R19	Rear Tyre Size:	255/45 R19
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,656.02	1,656.29	4,999.73	75.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,160.00	5,260.00	2,900.00	35.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	14,816.02	6,916.29	7,899.73	53.32
+ GST 7.00/7.00% (\$\$)	1,037.12	484.14	552.98	53.32
Nett Amount (\$\$)	15,853.14	7,400.43	8,452.71	53.32

INSPECTION

Date of Assignment:	19/05/2022		
Date Inspected:	20/05/2022	Inspected At:	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2022)
Parts:	M1-SUV	VOLKSWAGEN TIGUAN 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX7244L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED REAR BUMPER (UPPER)	Repair	1,586.27 FS	*- FS
2	1		*SPOILER PRIMED REAR BUMPER (CTR)	Broken	436.50 FS	*436.50 FS
3	1		*REAR DIFFUSOR BLACK REAR BUMPER (LOWER BLACK)	Broken	559.44 FS	*559.44 FS
4	1		*BUMPER (REINFORCEMENT)	Not Necessary	782.05 FS	*- FS
5	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	70.74 FS	*- FS
6	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	45.25 FS	*- FS
7	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	45.25 FS	*- FS
8	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	45.25 FS	*- FS
9	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	45.25 FS	*- FS
10	1		*DECORATIVE MOULDING BRIGH (CENTRE)	Cut	233.76 FS	*233.76 FS
11	1		*DECORATIVE MOULDING BRIGH (LH)	Not Necessary	179.92 FS	*- FS
12	1		*DECORATIVE MOULDING BRIGH (RH)	Not Necessary	183.84 FS	*- FS
13	1		*SENSOR BRACKET	Necessary	14.19 FS	*14.19 FS
14	1		*SENSOR BRACKET	Necessary	14.19 FS	*14.19 FS
15	1		*SENSOR BRACKET	Necessary	14.19 FS	*14.19 FS
16	1		*SENSOR BRACKET	Necessary	14.19 FS	*14.19 FS
17	1		*BONDING AGENT FOR PLASTIC	Necessary	68.85 FS	*68.85 FS
18	1		*2K-PLASTIC ADHESIVE	Necessary	85.94 FS	*85.94 FS
19	1		*SENSOR PRIMED	Not Necessary	190.18 FS	*- FS
20	1		*SEAL RING SATIN BLACK	Not Necessary	4.72 FS	*- FS
21	1		*INSCRIPTION BRIGHT CHROME (TIGUAN)	Necessary	104.40 FS	*104.40 FS
22	1		*VW SIGN BLACK HIGH GLOSS	Necessary	110.64 FS	*110.64 FS
23	1		*REAR WINDOW GLASS HEATED REAR W/SCREEN	Not Necessary	1,136.39 FS	*- FS
24	2		*1K WINDOW ADHESIVE	Not Necessary	102.88 FS	*- FS
25	1		*ALL PURPOSE CLEANER	Not Necessary	102.88 FS	*- FS
26	1		*PRIMER	Not Necessary	30.27 FS	*- FS
27	1		*ACTIVATOR	Not Necessary	26.27 FS	*- FS
28	2		*APPLICATOR	Not Necessary	22.32 FS	*- FS
29	1		*REAR WSCREEN SOLAR FILM	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,656.02** **1,656.29**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR.	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING.	New	480.00	480.00
3	SRPAY PAINTING.	New	3,200.00	2,400.00
4	LABOUR.	New	3,360.00	2,100.00
5	R&R REAR W/SCREEN.	New	840.00	0.00
Gross Labour Cost (\$)			8,160.00	5,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >