

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22004594/RPA3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SHC4018M**Insured Vehicle No :** SNC8738X

Date of Loss: 16/05/2022

Nature of Claim: TP

Claim No: MFL2022D0002571

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC4018M**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No: 2ZR8255387

Reg. Date: 12/12/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU703576147

Colour: Maroon

Odometer: 508441 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 6 mm

Rear Left Side: Sailun 6 mm

Front Right Side: Sailun 6 mm

Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,892.14	1,551.53	10,340.61	86.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,428.00	1,510.00	1,918.00	55.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,320.14	3,061.53	12,258.61	80.02
Approved Total (Overridden) (S\$)		2,750.00		
Nett Amount (S\$)	15,320.14	2,750.00	12,570.14	82.05
+ Loss of Use (7.0 x S\$40.00/day) (S\$)		280.00		
+ Car Rental (7.0 x S\$108.61/day) (S\$)		760.27		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,797.27		
Global Sum Settlement (S\$)		3,790.00		

INSPECTION

Date of Assignment: 17/05/2022

Date Inspected: 18/05/2022 Inspected At:

 Strides Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2022)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4018M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FENDER REAR LH (DISC 25%)	Bent	824.80 F	*618.60 F
2	1		*PANEL SUB-ASSY ,REAR DOOR ,LH (DISC 25%)	Bent	1,243.90 F	*932.93 F
3	1		*STICKER PETROL ONLY	Not Necessary	7.80 F	*- F
4	1		*LID ASSY ,FUEL FILLER OPENING	Not Necessary	164.10 F	*- F
5	1		*HUB & BEARING ASSY WITH SPEED SENSOR ,REAR	Not Necessary	610.20 F	*- F
6	1		*TYRE	Not Necessary	126.74 F	*- F
7	2		*HUB & BEARING ASSY ,RH & LH	Not Necessary	554.20 F	*- F
8	1		*LINER REAR FENDER ,LH	Not Necessary	135.80 F	*- F
9	2		*PATCH SIDE PANEL REAR END ,LH & RH	Not Necessary	33.70 F	*- F
10	2		*REAR DOOR SPEAKER ASSY ,RADIO RH & LH	Not Necessary	985.70 F	*- F
11	1		*WIRE ,REAR DOOR ,LH	Not Necessary	206.70 F	*- F
12	1		*DOOR REAR LOCK COVER	Not Necessary	8.90 F	*- F
13	1		*DOOR LOCK REAR ,LH	Not Necessary	544.70 F	*- F
14	1		*WEATHERSTRIP REAR DOOR LH	Not Necessary	174.40 F	*- F
15	1		*CHECK ASSY,REAR DOOR	Not Necessary	153.50 F	*- F
16	1		*MEMBER SUB-ASSY ,RAIL ROOT SIDE REAR LH	Not Necessary	279.20 F	*- F
17	1		*CHANNEL SUB-ASSY ,REAR DOOR GLASS ,LH	Not Necessary	27.20 F	*- F
18	1		*DOOR REAR WINDOW REGULATOR SUB-ASSY ,LH	Not Necessary	200.70 F	*- F
19	1		*DOOR REAR MOTOR ASSY POWER WINDOW	Not Necessary	768.60 F	*- F
20	1		*HINGE ASSY ,REAR DOOR ,LOWER LH	Not Necessary	73.30 F	*- F
21	1		*HINGE ASSY ,REAR DOOR ,UPPER LH	Not Necessary	83.30 F	*- F
22	1		*LENS & BODY ASSY ,RR BUMPER ,LH	Not Necessary	486.80 F	*- F
23	1		*PAD ,RR BUMPER ,CTR	Not Necessary	2.20 F	*- F
24	2		*PAD ,RR BUMPER ,RH & LH ,3	Not Necessary	3.80 F	*- F
25	2		*PAD ,RR BUMPER ,RH & LH ,2	Not Necessary	3.80 F	*- F
26	2		*PAD ,RR BUMPER ,RH & LH ,1	Not Necessary	3.80 F	*- F
27	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F
28	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Not Necessary	438.10 F	*- F
29	1		*REAR BUMPER GROMMET SCREW	Not Necessary	2.20 F	*- F
30	1		*ANTENNA ,ELECTRICAL KEY	Not Necessary	60.30 F	*- F
31	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
32	1		*GUARD ,RR BUMPER LOWER	Not Necessary	558.30 F	*- F
33	1		*CLIPS PIECE ,FRT & RR BUMPER	Not Necessary	1.50 F	*- F
34	1		*SEAL ,RR BUMPER ,LH	Not Necessary	85.20 F	*- F
35	1		*RETAINER ,RR BUMPER ,LH	Not Necessary	111.50 F	*- F
36	2		*STOPPER ,RR BUMPER ,RH & LH	Not Necessary	4.30 F	*- F
37	2		*SEAL ,RR BUMPER ARM ,RH & LH	Not Necessary	11.00 F	*- F
38	1		*MOULDING ASSY ,REAR DOOR BELT ,LH	Repair	109.80 F	*- F
39	1		*COVER ,RR BUMPER ASSY	Repair	423.90 F	*- F
40	1		*WHEEL, DISC	Repair	1,879.40 F	*- F

F=Franchise part.

Total Parts (S\$) 11,892.14 1,551.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	600.00
2	SPRAY PAINT	New	1,674.00	750.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO APPLY RUST -PROOFING ON AFFECTED AREA	New	100.00	40.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
6	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
8	TO REPLACE SUNDRY PARTS	New	100.00	0.00
9	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
Gross Labour Cost (S\$)			3,428.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >