

Vehicle Damage Assessment Report for [SHC4018M]

Estimate Created: 22/05/2022 15:03 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 29/09/2022 09:03 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Prius
Engine Type			
License Plate Number	SHC4018M	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review based on information provided by LKK Auto Consultants Pte Ltd
: Concluded lump sum repair cost of \$2750 with 5 working days.

Insurlogic 4 (29/09/2022 09:02)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
PANEL SUB-ASSY ,FENDER REAR LH		1	618.60	0.00 %	618.60
PANEL SUB-ASSY ,REAR DOOR ,LH		1	932.93	0.00 %	932.93
Parts Subtotal					1,551.53

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING & BODY WORK	RnR	600.00	0.00 %	600.00
TO APPLY RUST -PROOFING ON AFFECTED AREA	RnR	40.00	0.00 %	40.00
TO DO WHEEL ALIGNMENT /TYRE BALANCING	RnR	60.00	0.00 %	60.00
O TRANSFER DOOR MECHANISM	RnR	60.00	0.00 %	60.00

Paint

Description		Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINT		Full spray	750.00	0.00 %	750.00
Labor Rate	S\$ 50 / Hour			General Labor Subtotal	760.00
				Paint Labor Subtotal	750.00
				Labor Subtotal	1,510.00

Summary

Repair Cost	3,061.53
Discount(10 %)	(311.53)
	2,750.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,750.00