

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22004599/GQY3N2**Date:** 13/06/2022REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC21P00209000
Claimant Vehicle No : SHC7197J **Insured Vehicle No :** SNB7886M
 Date of Loss: 14/05/2022 Nature of Claim: TP Claim No: DMPC2200204H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC7197J**
 Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU662849
 Reg. Date: 28/07/2016 (Man. Year: 2016) Chassis No: KMHLB41UMGU092493
 Colour: Yellow Odometer: 0 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,448.48	243.36	2,205.12	90.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,030.00	950.00	47.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,428.48	1,273.36	3,155.12	71.25
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	4,428.48	1,000.00	3,428.48	77.42
+ GST 7.00/7.00% (S\$)	309.99	70.00	239.99	77.42
Nett Amount (S\$)	4,738.47	1,070.00	3,668.47	77.42

INSPECTION

Date of Assignment: 17/05/2022
 Date Inspected: 17/05/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jun 2022)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC7197J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR FENDER RH	Repair	2,171.40 FL	*- FL
2	1		*REAR BUMPER	Repair	553.00 FL	*- FL
3	10		*RR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
4	1		*RR WHEEL HUB CAP RH	Cut	214.20 FL	*214.20 FL
5	1		*RR DOOR COMFORT APP LOGO	Necessary	80.00 F	*80.00 FN
					Sub Total (S\$)	3,040.60 294.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	592.12 42.84
					- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00 8.00
					Total Parts (S\$)	2,448.48 243.36

F=Franchise part. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	280.00
2	SPRAY PAINTING CHARGE	New	800.00	750.00
3	REMOVE/REFIX UPHOLSTERY & CUSHION RR	New	120.00	0.00
4	TUFF KOTE	New	60.00	0.00
Gross Labour Cost (\$\$)			1,980.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >