

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE PTE LTD		F	Ref:	CS3/ASM22004623/Evy3e2	
	8 SHENTON WAY SINGAPORE 0688	[Date:	26/05/2022		
	ATTN : HO WINNIE		(Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 3416J	Veh. Inspected		FBR 6700E	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S2M03YW7	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		18/05/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA / AEROX GDR155R	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH3SG4620LJ078715	Colour		WHITE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/80-14	GOODYEAR		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-14	GOODYEAR		5 mm	
	L/H Rear Tyre				mm	
4.	•	Description of Damages				
	THE VEHICLE SUSBODY.	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.				
5.	General Information					
	Accident Date	14/04/2022	Inspect Date / T	ime	18/05/2022 (01:27 PM)	
	Survey held at	Blk 1005 Bukit Merah Lane 2 #01	-18			
	Repairer	FRIENDSHIP MOTOR CO				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22004623/Evy3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser