



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 126L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DISTORTED / TORN	2,324.01	2,324.01
1	FRONT BUMPER BEAM	NOT NECESSARY	715.00	-
1	FRONT BUMPER SIDE RETAINER N/S	CRACKED	136.21	136.21
2	FRONT BUMPER PDC SENSORS @\$293.49	SHORTED	586.98	586.98
1	FRONT BUMPER CENTRE GARNISH N/S	CRACKED	162.50	162.50
1	FRONT BUMPER CENTRE CHROME N/S	SCRATCHED	85.50	85.50
1	FRONT BUMPER LOGO	NECESSARY	62.00	62.00
1	FRONT BUMPER FOG LAMP GARNISH N/S	CRACKED	150.30	150.30
1	FRONT BUMPER SPONGE	TORN	182.40	182.40
1	SET FRONT BUMPER CLIPS & RIVET	NECESSARY	60.00	60.00
1	HEADLAMP LED ASSY N/S	CRACKED	8,032.82	8,032.82
1	HEADLAMP CONTROL UNIT N/S	SHORTED	966.00	966.00
1	FRONT FENDER N/S	DENTED	1,317.79	1,317.79
1	FRONT FENDER INNER SHIELD N/S	SERVICEABLE	245.50	-
1	SET FRONT FENDER INNER SHIELD CLIPS N/S	NECESSARY	50.00	50.00
1	FRONT FENDER LOWER CHROME N/S	NECESSARY	118.00	118.00
1	FRONT SPORT RIM N/S	TO REPAIR SEE LABOUR	1,300.00	-
	LESS 10% DISCOUNT		-1,649.50	-1,423.45
			14,845.51	12,811.06
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED FRONT PDC SENSOR.		100.00	80.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO CONDUCT WHEEL ALIGNMENT.		100.00	60.00
	TO SPRAY CERAMIC COATING.		500.00	400.00
	TO DIAGNOSTIC & REPROGRAMME SYSTEM.		1,500.00	1,300.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SPORT RIM N/S.		1,000.00	800.00

Report Ref No. CS/TP22004625/Uqce2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,000.00	800.00
			4,330.00	3,490.00
GRAND TOTAL			19,175.51	16,301.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CS/TP22004625/Uqce2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.