

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9519U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER COVER	CUT	481.10	481.10
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET LH	NECESSARY	28.00	28.00
1	FRT BUMPER BRACKET TOP LH	NOT NECESSARY	35.00	-
1	FRT BUMPER CENTRE MOULDING UPPER	SERVICEABLE	368.50	-
1	FRT BUMPER MOULDING LH	SERVICEABLE	93.60	-
1	FRT BUMPER LOWER GRILLE	SERVICEABLE	186.90	-
1	RADIATOR GRILLE	SCRATCHED	1,409.10	1,409.10
1	HEADLAMP SUPPORT PANEL ASSY	SERVICEABLE	949.30	-
1	DAY LIGHT LH	SERVICEABLE	642.50	-
1	HEADLAMP LH	SERVICEABLE	2,110.30	-
1	FRT BUMPER REINFORCEMENT	SERVICEABLE	1,136.70	-
1	FRT BUMPER LIP	SCRATCHED	35.10	35.10
1	FRT LOWER GRILLE MOULDING	SCRATCHED	186.90	186.90
1	FRT BUMPER SPONGE	SERVICEABLE	186.90	-
	LESS 20% DISCOUNT		-1,574.38	-432.44
			6,297.52	1,729.76
	SPECIAL NETT ITEMS			
1	FRT NUMBER PLATE WITH TRIM COVER (SN)	CRACKED	55.00	55.00
			55.00	55.00
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TUFF KOTE.		60.00	30.00
	CHECK LIGHTING / WIRING.		60.00	30.00
			1,220.00	660.00
	GRAND TOTAL		7,572.52	2,444.76

Report Ref No. NS/INC22004636/Vvcn2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		2,444.76
(CONFIRMED)		

Report Ref No. NS/INC22004636/Vvcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser