



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 7613B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	381.40	-
1	FRONT FENDER QUARTER GLASS LH (CONSISTENT)	SHATTERED	241.80	241.80
1	FRONT FENDER QUARTER GLASS MOULDING LH (CONSISTENT)	NECESSARY	72.00	72.00
1	FRONT FENDER QUARTER GLASS OUTER GARNISH LH (CONSISTENT)	CUT	83.20	83.20
1	FRONT FENDER QUESTER GLASS INNER GARNISH LH (CONSISTENT)	DEFORMED	138.50	138.50
1	FRONT DOOR LH (CONSISTENT)	DENTED	781.90	781.90
1	FRONT DOOR BLACK TAPE LH (CONSISTENT)	NECESSARY	51.20	51.20
1	FRONT DOOR WINDOW GLASS OUTER MOULDING LH (CONSISTENT)	NOT NECESSARY	128.00	-
1	FRONT SIDE MIRROR LH (CONSISTENT)	CRACKED	502.30	502.30
1	FRONT SIDE MIRROR COVER LH (CONSISTENT)	MISSING	92.80	92.80
	LESS 20% DISCOUNT		-494.62	-392.74
			1,978.48	1,570.96
<u>SPECIAL NETT ITEMS</u>				
1	FRONT FENDER QUARTER GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	FRONT FENDER QUARTER GLASS INNER GARNISH CLIP (SN) (CONSISTENT)	NECESSARY	30.00	20.00
1	FRONT FENDER INNER SHIELD CLIP (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT DOOR INNER TRIM BOARD CLIP (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			170.00	60.00
<u>LABOUR</u>				
	TO CHECK WIRINGS.		80.00	30.00
	TO REMOVE AND REPLACE FRONT FENDER GLASS.		150.00	60.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISH, SEATS ETC.		180.00	60.00
	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		600.00	400.00

Report Ref No. CS/ASM22004640/Aty3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINTING ON AFFECTED AREA.		600.00	500.00
			1,610.00	1,050.00
GRAND TOTAL			3,758.48	2,680.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS/ASM22004640/Aty3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.