

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004645/UTY3M4**Date:** 01/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00122132101
Claimant Vehicle No :	GX2922S	Insured Vehicle No :	GBF5200B
Date of Loss:	12/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203351/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX2922S	Engine No:	YS23356241A
Make & Model:	NISSAN NAVARA, 2.3 D CAB 7AT (A)	Chassis No:	MNTAB4D23Z0000078
Reg. Date:	30/06/2017 (Man. Year: 2017)	Odometer:	188595 km
Colour:	Silver		
Engine Capacity:	2298 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,503.32	1,336.12	167.20	11.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	970.00	640.00	330.00	34.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,473.32	1,976.12	497.20	20.10
Approved Total (Overridden) (\$\$)		1,700.00		
Nett Amount (\$\$)	2,473.32	1,700.00	773.32	31.27

INSPECTION

Date of Assignment:	18/05/2022		
Date Inspected:	26/05/2022	Inspected At:	Sin Hwee Motor Pte Ltd (HQ) Blk 3023A, Ubi Road 1, #01-59 Singapore 408717
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Jun 2022)	
Parts:	N/A	NISSAN NAVARA 2.3 D CAB 7AT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX2922S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY - NETT	Bent	1,206.80 FL	*1,206.80 FL
2	1		*NAVARA LGO - NETT	Serviceable	58.00 FL	*- FL
3	1		*REVERSE SENSOR (1SET)	Shorted	280.00 FS	*200.00 FS
4	1		*REAR NUMBER PLATE	Bent	45.00 FS	*30.00 FS
5	1		*70KM STICKER	Necessary	20.00 FS	*10.00 FS
6	1		*5 PAX STICKER	Necessary	20.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,629.80	1,456.80
- List Item Discount on L Items 10.00/10.00% (\$)	126.48	120.68
Total Parts (\$)	1,503.32	1,336.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESTORE INNER PANEL AND BRACKETS INCLUDE KNOCKING AND WELDING. TO REPLACE, INSTALL AND ALIGN REAR BUMPER.	New	450.00	400.00
2	TO SPRAY PAINT REAR TAILGATE.	New	400.00	200.00
3	TO SUPPLY FITTINGS AND INSTALL REVERSE SENSOR.	New	120.00	40.00
Gross Labour Cost (\$)			970.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >