

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004648/BVY3Q2**Date:** 13/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00167682100

Claimant Vehicle No : SDB5289T **Insured Vehicle No :** SJV5698U

Date of Loss: 15/05/2022 Nature of Claim: TP Claim No: SNM22D203349/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDB5289T**

Make & Model: MERCEDES-BENZ E250, 2.0 EXCLUSIVE (R18 LED) (A) Engine No: 27492031688871

Reg. Date: 22/01/2019 (Man. Year: 2018) Chassis No: WDD2130452A569837

Colour: Black Odometer: 170478 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/40 R18 Rear Tyre Size: 275/40 R18

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,093.15	8,582.40	7,510.75	46.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	1,540.00	3,680.00	70.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,313.15	10,122.40	11,190.75	52.51
Approved Total (Overridden) (S\$)		8,100.00		
Nett Amount (S\$)	21,313.15	8,100.00	13,213.15	62.00

INSPECTION

Date of Assignment: 18/05/2022

Date Inspected: 19/05/2022 Inspected At: 1 SIN MING IND EST SECT C #01-117
Repairer: IGNITE MOTOR (HQ)

Estimated Period of Repair: 9.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Sep 2022)

Parts: 143 MERCEDES-BENZ E250 2.0 EXCLUSIVE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDB5289T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,293.00 FL	*2,293.00 FL
2	1		*BOOTLID E250 EMBLEM	Necessary	92.00 FL	*92.00 FL
3	1		*BOOTLID CENTRE EMBLEM	Necessary	67.00 FL	*67.00 FL
4	1		*BOOTLID CENTRE EMBLEM LOCK CLIPS	Not Necessary	19.50 FL	*- FL
5	1		*BOOTLID 9 G-TRONIC EMBLEM	Necessary	112.00 FL	*112.00 FL
6	1		*BOOTLID LOCK	Not Damaged	318.00 FL	*- FL
7	1		*BOOTLID LOCK GARNISH	Not Damaged	108.00 FL	*- FL
8	1		*BOOTLID LOCK CATCH	Not Damaged	88.00 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Not Damaged	248.50 FL	*- FL
10	1		*REAR BUMPER	Dented	1,874.30 FL	*1,874.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
12	1		*SET REAR BUMPER RIVETS	Not Necessary	50.00 FL	*- FL
13	1		*REAR BUMPER CENTRE BRACKET	Broken	258.00 FL	*258.00 FL
14	1		*REAR BUMPER RH LOWER BRACKETS	Not Necessary	34.00 FL	*- FL
15	1		*REAR BUMPER LH LOWER BRACKETS	Not Necessary	34.00 FL	*- FL
16	1		*REAR BUMPER LOWER CHROME MOULDING	Broken	345.00 FL	*345.00 FL
17	1		*REAR BUMPER LOWER LID	Dented	674.00 FL	*674.00 FL
18	1		*REAR BUMPER LOWER SECTION BRACKET	Not Damaged	46.00 FL	*- FL
19	1		*REAR BUMPER RH REFLECTOR	Broken	132.00 FL	*132.00 FL
20	1		*REAR BUMPER LH REFLECTOR	Broken	132.00 FL	*132.00 FL
21	1		*REAR BUMPER REINFORCEMENT	Bent	846.00 FL	*836.00 FL
22	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Damaged	234.00 FL	*- FL
23	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Scratched	234.00 FL	*234.00 FL
24	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Scratched	234.00 FL	*234.00 FL
25	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Not Damaged	234.00 FL	*- FL
26	4		*REAR BUMPER REVERSE SENSOR O-RINGS	Necessary	72.00 FL	*72.00 FL
27	4		*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	104.00 FL	*104.00 FL
28	1		*REAR BUMPER RH SIDE RETAINER	Necessary	34.00 FL	*34.00 FL
29	1		*REAR BUMPER LH SIDE RETAINER	Necessary	34.00 FL	*34.00 FL
30	1		*REAR BUMPER TOWING COVER	Dislodged	79.00 FL	*79.00 FL
31	1		*REAR BUMPER SMART OPENER CONTROL UNIT	Not Damaged	316.00 FL	*- FL
32	2		*REAR BUMPER SMART OPENER SENSOR	Not Damaged	290.00 FL	*- FL
33	1		*REAR BUMPER RH EXHAUST CHROME	Cut	231.00 FL	*231.00 FL
34	1		*REAR BUMPER RH EXHAUST CHROME BRACKET	Not Necessary	56.00 FL	*- FL
35	1		*REAR BUMPER LH EXHAUST CHROME	Not Damaged	231.00 FL	*- FL
36	1		*REAR BUMPER LH EXHAUST CHROME BRACKET	Not Damaged	56.00 FL	*- FL
37	1		*RH TAILLAMP ASSY	Broken	834.00 FL	*736.00 FL
38	1		*RH TAILLAMP LOWER BRACKET	Not Necessary	78.00 FL	*- FL
39	1		*RH TAILLAMP SIDE GARNISH	No such part	48.00 FL	*- FL
40	1		*SET RH TAILLAMP SIDE GARNISH CLIPS	No such part	28.00 FL	*- FL
41	1		*RH TAILLAMP PANEL	Not Damaged	202.00 FL	*- FL
42	1		*LH TAILLAMP ASSY	Broken	834.00 FL	*736.00 FL
43	1		*LH TAILLAMP LOWER BRACKET	Not Necessary	78.00 FL	*- FL
44	1		*LH TAILLAMP SIDE GARNISH	No such part	48.00 FL	*- FL
45	1		*SET LH TAILLAMP SIDE GARNISH CLIPS	No such part	28.00 FL	*- FL
46	1		*LH TAILLAMP PANEL	Not Damaged	202.00 FL	*- FL

Report was unsubmitted during this print-out.

9/13/22, 2:11 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*END PANEL	Repair	1,539.00 FL	*- FL
48	1		*END PANEL INNER GARNISH	Broken	167.00 FL	*167.00 FL
49	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	60.00 FL	*30.00 FL
50	1		*REAR FLOOR PANEL TOP COVER	Not Damaged	413.50 FL	*- FL
51	1		*REAR RH FENDER INNER TRIM	Not Damaged	455.30 FL	*- FL
52	1		*SET REAR RH FENDER INNER TRIM CLIPS	Not Damaged	60.00 FL	*- FL
53	1		*REAR LH FENDER INNER TRIM	Not Damaged	455.30 FL	*- FL
54	1		*SET REAR LH FENDER INNER TRIM CLIPS	Not Damaged	60.00 FL	*- FL
55	1		*EXHAUST SILENCER	Not Damaged	1,731.10 FL	*- FL
56	1		*EXHAUST SILENCER GASKET	Not Damaged	62.00 FL	*- FL
57	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
58	1		*END PANEL JOINT SEALANT	Not Necessary	70.00 FS	*- FS
59	1		*RH TAILLAMP PANEL JOINT SEALANT	Not Necessary	28.00 FS	*- FS
60	1		*RH TAILLAMP PANEL JOINT SEALANT	Not Necessary	28.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,859.50	9,536.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,766.35	953.60
Total Parts (\$\$)					16,093.15	8,582.40
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGED BODYPARTS ,TO PANEL BEATING CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	2,000.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,600.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	150.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	180.00	0.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	180.00	60.00
6	REMOVE AND REPLACE REAR INNER TRIMS ,GARNISH AND BOARDS TO ASSIST REPAIR	New	450.00	0.00
7	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	480.00	0.00
8	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO NEW BOOTLID	New	180.00	80.00
Gross Labour Cost (\$)			5,220.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >