



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDS 4333R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER FASCIA	BENT	3,816.00	3,816.00
1	REAR BUMPER LOWER SPOILER	CRACKED	1,272.00	1,272.00
1	REAR BUMPER LOWER GRILLE	SERVICEABLE	804.50	-
1	REAR BUMPER "GTR" EMBLEM	NECESSARY	214.40	214.40
1	REAR BUMPER REINFORCEMENT	BENT	1,252.00	1,252.00
1	REAR BUMPER REVERSE CAMERA	SERVICEABLE	300.00	-
			7,658.90	6,554.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NO. PLATE (SN)	CRACKED	40.00	20.00
1	REAR BUMPER SPONGE (SN)	CRACKED	264.20	264.20
			304.20	284.20
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY REPLACED PARTS.		400.00	300.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS.		500.00	250.00
			900.00	550.00
	GRAND TOTAL		8,863.10	7,388.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,250.00

Report Ref No. CS/FCI22004651/Kty3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.