

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22004656/UPA3Q2**Date:** 06/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210140998
<b>Claimant Vehicle No :</b>	SGC37X	<b>Insured Vehicle No :</b>	SNC9165S
Date of Loss:	11/05/2022	Nature of Claim:	TP
		Claim No:	5023488996SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGC37X</b>	Engine No:	2AR1069054
Make & Model:	LEXUS ES300H, 2.5 Luxury (A)	Chassis No:	JTHBW1GG902060961
Reg. Date:	01/09/2014 (Man. Year: 2014)	Odometer:	200827 km
Colour:	White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,626.97	3,090.33	3,536.64	53.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,220.00	1,280.00	51.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,126.97</b>	<b>4,310.33</b>	<b>4,816.64</b>	<b>52.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>(S\$)</b>	9,126.97	3,400.00	5,726.97	62.75
<b>+ GST 7.00/7.00% (S\$)</b>	638.89	238.00	400.89	62.75
<b>Nett Amount (S\$)</b>	<b>9,765.86</b>	<b>3,638.00</b>	<b>6,127.86</b>	<b>62.75</b>
<b>+ Car Rental (4.0 x S\$150.00/day + 7.00% GST) (S\$)</b>		642.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>4,282.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,280.00</b>		

INSPECTION

Date of Assignment:	18/05/2022		
Date Inspected:	18/05/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented/Bent	1,143.70 FN	*1,143.70 FN
2	1		*BOOTLID LOCK	Serviceable	472.00 FN	*- FN
3	1		*BOOTLID LEXUS BADGE	Not Necessary	173.70 FN	*- FN
4	1		*BOOTLID ES300H BADGE	Necessary	75.00 FN	*75.00 FN
5	1		*BOOTLID EMBLEM BADGE	Necessary	66.90 FN	*66.90 FN
6	1		*BOOTLID WEATHERSTRIP	Not Necessary	226.00 FN	*- FN
7	1		*REAR BUMPER	Dented/Deformed	999.00 FN	*999.00 FN
8	1		*REAR BUMPER REINFORCEMENT	Bent	621.00 FN	*621.00 FN
9	2		*REAR BUMPER BRACKET	Not Necessary	130.00 FN	*- FN
10	2		*REAR BUMPER SIDE RETAINER	Not Necessary	274.60 FN	*- FN
11	1		*REAR BUMPER SPONGE	Torn	120.00 FN	*120.00 FN
12	1		*REAR BUMPER PARKING SENSOR	O/s Shorted	1,893.20 FN	*408.10 FN
			4 Pcs			
13	2		*REAR BUMPER REFLECTOR	Not Necessary	120.00 FN	*- FN
14	1		*REAR END PANEL	Repair	752.00 FN	*- FN
15	1		*REAR END PANEL INNER TRIM	Not Necessary	296.20 FN	*- FN
					<b>Sub Total (S\$)</b>	<b>7,363.30      3,433.70</b>
					<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	<b>736.33      343.37</b>
					<b>Total Parts (S\$)</b>	<b>6,626.97      3,090.33</b>

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
3	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	120.00	60.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	200.00	30.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR	New	100.00	60.00
6	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	900.00	400.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,500.00</b>	<b>1,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >