



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM21012657/Tty3-1				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS/ASM21012657/Tty3-1 Date: 17/01/2022 17/05/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHA 5750K	Veh. Inspected	5431S	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M03O1W	Excess (\$)	0.00	
Assign From	LOH CYNTHIA HENG XIN YI (SFAH ONG)	Assign Date	17/12/2021 17/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI EVO	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour	WHITE	
Odometer	116992 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	NEXEN	6 mm	
L/H Front Tyre	245/40 R18	NEXEN	6 mm	
R/H Rear Tyre	245/40 R18	NEXEN	6 mm	
L/H Rear Tyre	245/40 R18	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
5. General Information				
Accident Date	08/12/2021	Inspection Date	17/12/2021	
Survey held at	160 Sin Ming Drive #05-18, Sin Ming Autocity			
Repairer	CARFEELS PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,500				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		