

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004660/UPA3Q2**Date:** 25/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800069980
Claimant Vehicle No :	SKT9046Z	Insured Vehicle No :	SMA9640J
Date of Loss:	17/05/2022	Nature of Claim:	TP
		Claim No:	6864929150SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT9046Z	Engine No:	2ZRB574803
Make & Model:	TOYOTA WISH, 1.8 X CVT (A)	Chassis No:	ZGE206023348
Reg. Date:	25/06/2015 (Man. Year: 2015)	Odometer:	138566 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,065.00	3,196.51	1,868.49	36.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,820.00	1,240.00	40.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,125.00	5,016.51	3,108.49	38.26
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	8,125.00	4,000.00	4,125.00	50.77
+ GST 7.00/7.00% (S\$)	568.75	280.00	288.75	50.77
Nett Amount (S\$)	8,693.75	4,280.00	4,413.75	50.77
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,031.00		
Global Sum Settlement (S\$)		5,000.00		

INSPECTION

Date of Assignment:	18/05/2022	
Date Inspected:	18/05/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	584.70 FL	*584.70 FL
2	1		*FRONT BUMPER SIDE RETAINER	N/S Bent / Cracked	119.14 FL	*59.57 FL
3	1		*FRONT BUMPER REINFORCEMENT	Twisted	305.20 FL	*305.20 FL
4	1		*FRONT BUMPER SPONGE	Torn	100.00 FL	*100.00 FL
5	1		*N/S FRONT BUMPER FOGLAMP COVER -SMALL	Not Necessary	95.00 FL	*- FL
6	1		*N/S FRONT BUMPER FOGLAMP COVER -BIG	Not Necessary	145.00 FL	*- FL
7	1		*N/S FRONT FENDER	Buckled	988.40 FL	*845.11 FL
8	1		*N/S FRONT FENDER INNER SHIELD	Deformed	178.20 FL	*178.20 FL
9	1		*O/S FRONT FENDER INNER SHIELD	Not Necessary	178.20 FL	*- FL
10	1		*RADIATOR GRILLE	Cracked	398.00 FL	*398.00 FL
11	1		*BONNET LOGO EMBLEM	Not Necessary	92.00 FL	*- FL
12	1		*AIR CLEANER AIR DUCT	Not Necessary	85.70 FL	*- FL
13	1		*AIR CLEANER AIR DUCT PIPE	Not Necessary	128.00 FL	*- FL
14	1		*N/S FRONT LOWER ARM	Bent	760.10 FL	*665.10 FL
15	1		*N/S FRONT KNUCKLE ARM	Bent	628.40 FL	*605.50 FL
16	1		*N/S FRONT HUB	Bent	220.00 FL	*220.00 FL
17	1		*N/S FRONT WHEEL BEARING	Damaged	167.30 FL	*167.30 FL
18	1		*N/S FRONT SHOCK ABSORBER	Not Necessary	340.00 FL	*- FL
19	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
20	1		*SET N/S FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*50.00 FS
21	1		*SET O/S FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
22	1		*N/S FRONT RIM	Repair	500.00 FS	*- FS
23	1		*N/S FRONT TYRE	Serviceable	250.00 FS	*- FS
24	1		*BTL COOLANT	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,443.34	4,228.68
- List Item Discount on L Items 25.00/25.00% (S\$)	1,378.34	1,032.17
Total Parts (S\$)	5,065.00	3,196.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT AND WIRING	New	50.00	20.00
2	COMPUTERIZED WHEEL ALIGNMENT	New	120.00	80.00
3	ANTI-RUST AND BODY SEALANT	New	120.00	0.00
4	TO VACUUM ,REOIL AND REGAS AIR CON	New	120.00	0.00
5	REPLACE FRONT UNDERCARRIAGE	New	250.00	120.00
6	LABOUR /PANEL BEATING ,REPAIR SUPPORT PANEL AND REPLACE PARTS	New	900.00	600.00
7	SPRAY PAINTING 1)BUMPER 2)REINFORCEMENT 3) NS FENDER 4) OS FENDER 5) BONNET 6) SUPPORT PANEL	New	1,500.00	1,000.00
Gross Labour Cost (\$)			3,060.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >