

ASS. REC. BY: Thayan

REF:

CS6/AIS22004663/00Y3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. 2022 22004770SLSum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 78k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMS2660A Yr Regn: 27/2/19Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: hla Cerato c.c 1591Colour: red A/C: Insured / Std / NI / NASp. Reading: 82245 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: hnpaf3416mk5025353Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sincera

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 3/5/22 D.O.I. 18/5/22 1730Survey held at DesktopDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

mu: 78krebate: 27/144nu: 50856

11/8/22 LS \$2800 confirmed by email (Red 2713.80, 49%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 11/8/22-typist

Report Format :

Lump Sum / T.B.H (\$ 2800)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

932C

SMJ2660A

No

20 May 2022

KIA

CERATO 1.6(A) EX

Red

2018

G4FGJH714411

KNAF3416MK5025353

93.8 kW (125 bhp)

\$13,634.00

27 Feb 2019

27 Feb 2019

0

\$13,634.00

Yes

26 Feb 2029

\$10,225.00

26 Feb 2029

A - Car up to 1600cc & 97kW (130bhp)

10

\$25,000.00

\$16,919.00

\$27,144.00

6817

The information contained herein is correct as at 20 May 2022

OK

47: 10.56

12

= 875

64/159/81

875 x 81 = 70875

70875 + 6817

= 77692

= 78h

78h - 27144

= 50856

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: SPMF1000000449

Accident Date : 05.05.2022

Date: 14.05.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Kia Cerato" Reg. No SMJ2660A			
1pc	Front Bumper	1.50	285.00 / cut
1pc	Front Bumper Clips		18.00 / nec
1pc	Front Bumper Bracket RH		12.00 / nec
1pc	Front Bumper Sponge		115.00 ^
1pc	Front Bumper Reinforcement		190.00 ^
1pc	Front Bumper Beam		50.00 ^
1pc	Front Bumper Emblem		20.00 / nec
1pc	Front Bumper Corner Retainer RH		12.00 / nec
1pc	Front Bumper Signal Lamp RH		80.00 / cut
1pc	Front Bumper Side Air Grille RH		8.00 / cut
1pc	Front Bumper Lower Lip		130.00 / cut
1pc	Front Bumper Lower Lip Garnish		60.00 / cut
1pc	Front Bumper Fog Lamp RH		120.00 / cut
1pc	Front Bumper Air Duct RH		10.00 / cut
1pc	Headlamp RH		530.00 x svc
1pc	Headlamp Lower Bracket		35.00 / cut
1pc	Grille		130.00 / cut
1pc	Front Fender RH		160.00 / cut
1pc	Front Fender Shield		58.00 x svc
1pc	Wiper Tank		65.00 x svc
1pc	Wiper Tank Motor		45.00 x svc
1pc	Support Panel		325.00 ^
1pc	Front Wheel Rim		350.00 / scr
1pc	Front Shock Absorber		115.00 x svc
1pc	Front Knuckle Arm		130.00 x svc
1pc	Front Knuckle Arm Bearing		180.00 x svc
1pc	Front Lower Arm		125.00 x svc
	Cost Plus 10%		3,358.00
			335.80
			3,693.80
	To Conduct Electrical Check, Focus Headlamp		30.00 / to
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00 x nwn
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 x nwn
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		180.00 x nwn
		C/F	4,083.80

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Allianz Global Corporate & Specialty SE, Singapore Branch

Policy No: SPMF1000000449

Accident Date : 05.05.2022

Date: 14.05.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Kia Cerato" Reg. No SMJ2660A		
	To Conduct Computerize Wheel Alignment Test	B/F	4,083.80
	Labour Charge - Panel Beating, Repairing of Bonnet, Front Chassis, Front Fender Inner Panel & Part Replacement		80.00 XNN
	To Respray Affected Areas		700.00 400 600
			650.00 600
	Total :		5,513.80
<p>Thuan@lkhauto.com 82235769 18/5/22 1730 OP not authorise L/S repair scays wp</p>			
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p>			