



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2204624

INV Date 27/07/2022

Reference CC4/LPC22004665/Kpa3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. GBF 5485X

Insured Veh. GBD 2314L

Claim No. 21/22/22/VC05/025745

Policy No. Z21VC05007844

Accident Date 30/04/2022

Inspection Date 19/05/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22004665/Kpa3q2 Date: 27/07/2022 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBD 2314L	Veh. Inspected	GBF 5485X	
Policy No.	Z21VC05007844	Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/025745	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	18/05/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFHT02P900209071	Colour	YELLOW	
Odometer	162749 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	GRENLANDER	9 mm	
L/H Front Tyre	195 R15X8	GRENLANDER	9 mm	
R/H Rear Tyre	195 R15X8	GRENLANDER	9 mm	
L/H Rear Tyre	195 R15X8	GRENLANDER	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/04/2022	Inspection Date	19/05/2022	
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 5485X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	BENT	2,168.50	2,168.50
1	TAILGATE CENTRE LOGO	NECESSARY	72.90	72.90
1	TAILGATE CENTRE GARNISH	SERVICEABLE	149.60	-
1	TAILGATE LOCK	DENTED	289.60	289.60
1	TAILGATE INNER TRIMBOARD	SERVICEABLE	515.40	-
2	TAILLAMP ASSY -LH/RH @\$306.90	N/S CRACKED	613.80	306.90
1	TAILLAMP LOWER GARNISH -LH	SERVICEABLE	98.95	-
1	REAR END PANEL (INNER)	TO REPAIR SEE LABOUR	1,105.95	-
1	REAR END PANEL (OUTER)	BENT	442.90	442.90
1	REAR END PANEL TOP GARNISH	DENTED	118.95	118.95
1	REAR BUMPER	BENT	399.65	399.65
1	REAR BUMPER SIDE RETAINER -LH	SERVICEABLE	48.90	-
	LESS 25% DISCOUNT		-1,506.28	-949.85
			4,518.82	2,849.55
1	TAILGATE WEATHERSTRIP (50%) (SN)	CUT	408.90	204.45
	LESS 25% DISCOUNT		-102.23	-
			306.67	204.45
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	TAILGATE '70KM/H' STICKER (SN)	NECESSARY	25.00	15.00
1	SET REAR BUMPER SENSOR (SN)	DENTED	350.00	200.00
			435.00	255.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS .		150.00	120.00
	TO TRANSFER DAMAGED TAILGATE INTERIOR MECHANISM TO NEW TAILGATE.		120.00	60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PANEL BEAT AND STRAIGHTEN REAR FLOORBOARD PANEL ,REAR CHASSIS FRAME ,TO CUT AND WELD REAR END PANEL ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME.INCLUSIVE OF THE REPAIR OF REAR END PANEL (INNER).		1,500.00	700.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS .		1,000.00	500.00
	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS.		160.00	60.00
	TO SUPPLY AND PASTER LOGO ON TAILGATE.		680.00	400.00
			3,610.00	1,840.00
<b>GRAND TOTAL</b>			<b>8,870.49</b>	<b>5,149.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>5,149.00</b>

Report Ref No. CC4/LPC22004665/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBF 5485X

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. GBF 5485X

### RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 5485X

RE-INSPECTION





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

