



# T & C AUTOMOBILE ASSESSORS

KHOO TENG EK  
G/O MING HUA AUTO SERVICES  
160 Sin Ming Drive  
#02-16 Singapore 575722

REF : TC/2019/436

DATE : 1/3/2018

## VEHICLE SURVEY REPORT

### REFERENCE

Requested By : Workshop, on behalf of owner  
Date of Request : 20/2/2018  
Date of Accident : 18/2/2018  
Date of Inspection : 20/2/2018  
Inspected At : Ming Hua Auto Services  
160 Sin Ming Drive  
#02-16 Singapore 575722

### PARTICULARS OF VEHICLE

Vehicle Registration No : SLV7873T Make & Model : MITSUBISHI  
ATTRAGE 1.2 CVT  
Year Make : 2017 Colour : RED  
Engine No : 3A92UGN9691 Chassis No. : MMBSTA13AJH000894  
Engine Capacity : 1193cc

### CONDITION OF VEHICLE AND TYRES

General Condition : Good Mileage : 2949  
Brakes : Serviceable Modification : None  
Steering : Serviceable Handbrake : Serviceable

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>
Front RHS	Bridgestone	185/55R15	5
Front LHS	Bridgestone	185/55R15	5
Rear RHS	Bridgestone	185/55R15	6
Rear LHS	Bridgestone	185/55R15	6

### DESCRIPTION OF DAMAGES

The Vehicle sustained damages at the rear portion.  
(For information of damages, please refer to Parts/Labour/Photographs attached)

### INSTRUCTION

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.



# T & C AUTOMOBILE ASSESSORS

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vechile No : SLV7873T

Report No : TC/2019/436

<u>S/NO</u>	<u>QTY</u>	<u>DESCRIPTION</u>	<u>CONDITION/ REMARKS</u>	<u>REPAIRER'S ESTIMATES</u> S\$	<u>OUR ASSESSMENT</u> S\$
1	1	Front bumper	Deformed	1,096.40	1,096.40
2	1	Front bumper reinforcement	Bent	216.30	216.30
3	1	Front bumper bracket	Bent	171.50	171.50
4	1	Front bumper side retainer	Broken	86.70	86.70
5	1 set	Front bumper clips	Necessary	60.00	60.00
6	1	Front bumper lower grille	Broken/cut	277.90	277.90
7	1	Front grille	Broken/cut	486.20	486.20
8	1	Front grille badge	Necessary	48.50	48.50
9	1 set	Front grille clips	Necessary	50.00	50.00
10	1	Front support panel	Bent	787.90	787.90
11	1	Front LH foglamp	Cut	169.50	169.50
12	1	Front LH foglamp cover	Necessary	67.90	67.90
13	1	Front LH fender	Deformed	474.20	474.20
14	1	Front LH headlamp	Broken	896.30	896.30
				4,889.30	4,889.30
Less : Discount 10%				-488.93	-488.93
<b>Total :</b>				<b>4,400.37</b>	<b>4,400.37</b>
<b><u>SPECIAL NETT ITEMS</u></b>					
15	1	Front number plate and casing	Dented	80.00	80.00
				80.00	80.00
<b>Total Spare Parts :</b>				<b>4,480.37</b>	<b>4,480.37</b>



# T & C AUTOMOBILE ASSESSORS

## LABOUR CHARGES

Vehicle No : SLV7873T

Report No : TC/2019/436

<u>S/NO</u>	<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,700.00	1,400.00
2	To putty and respray painting on effected areas.	1,500.00	1,200.00
3	To check wiring and lightings.	120.00	80.00
4	To applied LTA permit, and sent vehicle to inspection centre for reseal of front number plate.	150.00	120.00
5	To apply undersealing.	200.00	150.00
<b>Total Labour Charges :</b>		<b>3,670.00</b>	<b>2,950.00</b>
<b>Total Spare Parts :</b>		<b>4,480.37</b>	<b>4,480.37</b>
<b>Total Repair Costs :</b>		<b>8,150.37</b>	<b>7,430.37</b>

### Assessor's Recommendation

Repairer Estimate : 8,150.37

Our Adjustment : 7,430.37

### Remarks

The repairer has agreed to undertake the repair of **S\$7,430.37**, with a repair period of 10 working days.

Surveyed By:

THAM KOK SANG



