



T & C AUTOMOBILE ASSESSORS

KHOO TENG EK
C/O MING HUA AUTO SERVICES
160 Sin Ming Drive
#02-16 Singapore 575722

REF : TC/2019/436

DATE : 1/3/2018

VEHICLE SURVEY REPORT

REFERENCE

Requested By : Workshop, on behalf of owner
Date of Request : 20/2/2018
Date of Accident : 18/2/2018
Date of Inspection : 20/2/2018
Inspected At : Ming Hua Auto Services
160 Sin Ming Drive
#02-16 Singapore 575722

PARTICULARS OF VEHICLE

Vehicle Registration No : SLV7873T Make & Model : MITSUBISHI
ATTRAGE 1.2 CVT
Year Make : 2017 Colour : RED
Engine No : 3A92UGN9691 Chassis No. : MMBSTA13AJH000894
Engine Capacity : 1193cc

CONDITION OF VEHICLE AND TYRES

General Condition : Good Mileage : 2949
Brakes : Serviceable Modification : None
Steering : Serviceable Handbrake : Serviceable

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>
Front RHS	Bridgestone	185/55R15	5
Front LHS	Bridgestone	185/55R15	5
Rear RHS	Bridgestone	185/55R15	6
Rear LHS	Bridgestone	185/55R15	6

DESCRIPTION OF DAMAGES

The Vehicle sustained damages at the rear portion.
(For information of damages, please refer to Parts/Labour/Photographs attached)

INSTRUCTION

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.



Annex A

T & C AUTOMOBILE ASSESSORS

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vechile No : SLV7873T

Report No : TC/2019/436

<u>S/NO</u>	<u>QTY</u>	<u>DESCRIPTION</u>	<u>CONDITION/ REMARKS</u>	<u>REPAIRER'S ESTIMATES</u> S\$	<u>OUR ASSESSMENT</u> S\$
1	1	Front bumper	Deformed	1,096.40	1,096.40 706
2	1	Front bumper reinforcement	Bent	216.30	216.30
3	1	Front bumper bracket	Bent	171.50	171.50 X NS
4	1	Front bumper side retainer	Broken	86.70	86.70
5	1 set	Front bumper clips	Necessary	60.00	60.00 40
6	1	Front bumper lower grille	Broken/cut	277.90	277.90 X NN
7	1	Front grille	Broken/cut	486.20	486.20
8	1	Front grille badge	Necessary	48.50	48.50
9	1 set	Front grille clips	Necessary	50.00	50.00 30
10	1	Front support panel	Bent	787.90	787.90 X R
11	1	Front LH foglamp	Cut	169.50	169.50
12	1	Front LH foglamp cover	Necessary	67.90	67.90 X SVC
13	1	Front LH fender	Deformed	474.20	474.20
14	1	Front LH headlamp	Broken	896.30	896.30 663
				4,889.30	4,889.30
Less : Discount 10%				-488.93	-488.93
Total :				4,400.37	4,400.37
SPECIAL NETT ITEMS					
15	1	Front number plate and casing	Dented	80.00	80.00 40
				80.00	80.00
Total Spare Parts :				4,480.37	4,480.37



Annex B

T & C AUTOMOBILE ASSESSORS**LABOUR CHARGES**

Vechile No : SLV7873T

Report No : TC/2019/436

<u>S/NO</u>	<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>	
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,700.00	1,400.00	600
2	To putty and respray painting on effected areas.	1,500.00	1,200.00	600
3	To check wiring and lightings.	120.00	80.00	30
4	To applied LTA permit, and sent vehicle to inspection centre for reseal of front number plate.	150.00	120.00	100
5	To apply undersealing.	200.00	150.00	50
Total Labour Charges :		3,670.00	2,950.00	
Total Spare Parts :		4,480.37	4,480.37	
Total Repair Costs :		8,150.37	7,430.37	

Assessor's Recommendation

Repairer Estimate : 8,150.37
Our Adjustment : 7,430.37

Remarks

The repairer has agreed to undertake the repair of **S\$7,430.37**, with a repair period of 10 working days.

Surveyed By:

THAM KOK SANG

5 days