



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 8826G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR WINDSCREEN (CONSISTENT)	NOT NECESSARY	1,288.20	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	145.80	-
1	TAILGATE (CONSISTENT)	TO REPAIR SEE LABOUR	3,066.20	-
1	TAILGATE OUTER HANDLE (CONSISTENT)	NOT NECESSARY	450.00	-
1	TAILGATE REAR LOGO (CONSISTENT)	NOT NECESSARY	65.00	-
1	TAILGATE "QASHQAI" EMBLEM (CONSISTENT)	NECESSARY	85.00	78.50
1	TAILGATE EMBLEM (CONSISTENT)	NECESSARY	92.00	88.00
1	TAILGATE INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	595.60	-
1	SET TAILGATE INNER TRIM BOARD CLIPS (CONSISTENT)	NOT NECESSARY	45.00	-
1	TAILGATE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	265.00	-
1	SET TAILGATE REVERSE CAMERA (CONSISTENT)	NOT NECESSARY	580.00	-
1	REAR BUMPER (CONSISTENT)	DENTED	891.00	876.40
1	REAR BUMPER TOW COVER (CONSISTENT)	NOT NECESSARY	85.00	-
2	REAR BUMPER REFLECTORS @\$85.00 (CONSISTENT)	N/S CRACKED	170.00	62.00
2	REAR BUMPER SIDE RETAINERS @\$65.00 (CONSISTENT)	N/S BENT	130.00	25.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	45.00	39.00
1	REAR BUMPER SPONGE (CONSISTENT)	NOT FITTED	225.00	-
1	REAR BUMPER BEAM (CONSISTENT)	DENTED	721.00	691.50
2	REAR BUMPER BEAM BRACKETS @\$150.00 (CONSISTENT)	N/S BENT	300.00	141.00
1	REAR END PANEL (CONSISTENT)	DENTED	720.00	482.60
1	REAR END PANEL LOCK SENSOR (CONSISTENT)	NOT NECESSARY	122.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	480.00	-
2	REAR FENDERS @\$1150.00 (CONSISTENT)	TO REPAIR SEE LABOUR	2,230.00	-
2	REAR FENDER INNER TRIM BOARDS @\$455.00 (CONSISTENT)	NOT NECESSARY	910.00	-
2	REAR FENDER OUTER PROTECTORS @\$541.00 (CONSISTENT)	O/S TORN	1,082.00	481.00
2	REAR FENDER UNDER TRIMS @\$350.00 (CONSISTENT)	NOT NECESSARY	700.00	-

Report Ref No. CC4/ASM22004669/Upa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAILLAMPS @\$680.00 (CONSISTENT)	N/S CRACKED / O/S NOT NECESSARY	1,360.00	462.00
	LESS 10% DISCOUNT		-	-342.70
			16,848.80	3,084.30
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	TORN	280.00	200.00
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN INNER SEAL (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			430.00	250.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO TRANSFER TAILGATE MECHANISM.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX FUEL TANK.	NOT NECESSARY	100.00	-
	TO RESET & REPGOGRAMME SYSTEM.		180.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR FENDERS.		2,200.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,100.00
	TO SPRAY RUST PROOFING.		150.00	40.00
			5,030.00	2,170.00
<b>GRAND TOTAL</b>			<b>22,308.80</b>	<b>5,504.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,400.00</b>

Report Ref No. CC4/ASM22004669/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.