



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4169K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
2	CORNER END CAP @\$180.00	NECESSARY	360.00	360.00
3	SIDE STAINLESS STEEL FRAME PROFILE @\$580.00	BENT	1,740.00	1,740.00
1	SIDE DOOR ASSY	BROKEN	950.00	950.00
2	STAINLESS STEEL DOOR HINGE @\$150.00	BENT	300.00	300.00
10	DOOR RUBBER GASKET (METER) @\$55.00	NECESSARY	550.00	550.00
1	GRP BOARD INTERNAL	BROKEN	2,500.00	2,500.00
8	SIKA FORCE GLUE @\$85.00	NECESSARY	680.00	680.00
10	WHITE SILICON @\$40.00	NECESSARY	400.00	400.00
1	RIVET SET	NECESSARY	15.00	15.00
4	BLUE STYROFOAM @\$80.00	NECESSARY	320.00	320.00
	LESS 10% DISCOUNT		-	-781.50
			7,815.00	7,033.50
<b>LABOUR</b>				
	TO REPLACE INNER GRP BOARD (SKIN).		680.00	400.00
	TO REPLACE LH FREEZER DOOR & SIDE STAINLESS STEEL FRAME PROFILE.		1,000.00	600.00
	TO SPRAY PAINT LH SIDE FREEZER BOX.		500.00	300.00
	TO DISCHARGE & TOP UP REFRIGERANT.		250.00	180.00
	TO CONDUCT FREEZER LEAK DETECTION TEST.		350.00	200.00
			2,780.00	1,680.00
<b>GRAND TOTAL</b>			<b>10,595.00</b>	<b>8,713.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,000.00</b>
<b>LESS EXCESS</b>				<b>-600.00</b>
<b>NETT LIABILITY</b>				<b>6,400.00</b>

Report Ref No. CS/LPC22004673/Evy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.