

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAI	NCE BHD		Ref:	CS3/LPC22004678/Gqy3e2	
	300 BEACH ROAD SINGAPORE 1995	) #17-04/07 THE CONCOURSE 55		Date:	26/05/2022	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKU 502C	Veh. Inspected	ı	SLC 3367P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VP05/025810	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		18/05/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI / ASX 2.0	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JMFXTGA2WFZC13827	Colour		GREY	
	Odometer	66979 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/55R18	ROADSTONE		6 mm	
	L/H Front Tyre	225/55R18	ROADSTONE		6 mm	
	R/H Rear Tyre	225/55R18	ROADSTONE		6 mm	
	L/H Rear Tyre	225/55R18	ROADSTONE		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SU	USTAINED DAMAGES AT THE REAR PORTION.				
5.	5. General Information					
	Accident Date	16/05/2022	Inspect Date /	Time	18/05/2022 ( 04:00 PM )	
	Survey held at	KOMPRESSOR AUTOMOTIVE				
		8 KAKI BUKIT AVE 4 #02-48 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22004678/Gqy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**