



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 5972M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FORK ASSY	NOT NECESSARY	980.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	190.00	-
1	SET SIDE MIRROR	CUT	120.00	80.00
1	HANDLE-BAR	BENT	135.00	135.00
1	HANDLE-BAR BALANCER O/S	CUT	80.00	35.00
1	SET HANDLE GRIP	NOT NECESSARY	60.00	-
2	BRAKE LEVER	NOT NECESSARY	104.00	-
2	FOOTSTEP PANEL	O/S CUT / N/S NOT NECESSARY	510.00	130.00
2	FOOTSTEP PANEL LOWER COVER	O/S CUT / N/S NOT NECESSARY	340.00	105.00
1	SET FAIRING COVER	CUT	1,350.00	600.00
1	EXHAUST ASSY	DENTED	680.00	550.00
1	EXHAUST PROTECTOR	CUT	98.00	98.00
1	ENGINE MOUNTING	TWISTED	480.00	325.00
1	AIR FILTER COVER	GRAZED	155.00	75.00
1	RADIATOR COVER	CUT	180.00	108.00
1	REAR MUDGUARD	DISTORTED	168.00	148.00
1	REAR SIGNAL	NOT NECESSARY	180.00	-
1	REAR SIGNAL COVER-MATT	NOT NECESSARY	180.00	-
1	REAR ABSORBER	NOT NECESSARY	650.00	-
1	REAR RIM	NOT NECESSARY	680.00	-
	LESS 10% DISCOUNT		-732.00	-238.90
			6,588.00	2,150.10
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR NUMBER PLATE (SN)	BENT	38.00	30.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	REAR BOX (SN)	SERVICEABLE	480.00	-
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-

Report Ref No. CS/SMR22004681/Uty3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	"AEROX" EMBLEM (SN)	NECESSARY	60.00	60.00
			964.00	90.00
	LABOUR			
	TO PROVIDE WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR.		450.00	300.00
			1,010.00	300.00
GRAND TOTAL			8,562.00	2,540.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/SMR22004681/Uty3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.