

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004682/DNY3Q2**Date:** 12/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00197712100

Claimant Vehicle No : SMU9433K **Insured Vehicle No :** SGY6627M

Date of Loss: 17/04/2022 Nature of Claim: TP Claim No: SNM22D203366/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU9433K**

Make & Model: HONDA VEZEL HYBRID, 1.5 RS (A) Engine No: LEB5900646

Reg. Date: 30/09/2016 (Man. Year: 2016) Chassis No: RU31200642

Colour: Red Odometer: 175206 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,909.84	1,146.64	14,763.20	92.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,150.00	850.00	6,300.00	88.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,059.84	1,996.64	21,063.20	91.34
Approved Total (Overridden) (\$\$)		1,600.00		
(\$\$)	23,059.84	1,600.00	21,459.84	93.06
+ GST 7.00/7.00% (\$\$)	1,614.19	112.00	1,502.19	93.06
Nett Amount (\$\$)	24,674.03	1,712.00	22,962.03	93.06

INSPECTION

Date of Assignment: 18/05/2022

Date Inspected: 18/05/2022 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2022)
Parts:	M1-SUV	HONDA VEZEL HYBRID 1.5 RS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU9433K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,492.30 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	98.50 FL	*- FL
3	1		*BONNET STRIKER LOCK	Not Necessary	49.20 FL	*- FL
4	1		*BONNET INSULATOR	Not Necessary	122.30 FL	*- FL
5	2		*BONNET HINGE	Not Necessary	97.00 FL	*- FL
6	2		*HEAD LAMP RH	Not Necessary	3,164.00 FL	*- FL
7	2		*HEAD LAMP LOWER BRACKET RH	Not Necessary	35.00 FL	*- FL
8	1		*HEAD LAMP WIRE HARNESS	Not Necessary	980.00 FL	*- FL
9	1		*FRONT GRILLE	Not Necessary	1,794.00 FL	*- FL
10	1		*FRONT GRILLE GARNISH	Not Necessary	380.00 FL	*- FL
11	1		*FRONT GRILLE LOGO	Not Necessary	23.40 FL	*- FL
12	1		*FRONT GRILLE CHROME	Not Necessary	385.00 FL	*- FL
13	1		*FRONT BUMPER	Distorted / Mtg Broken	801.70 FL	*801.70 FL
14	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	35.00 FL	*- FL
15	1		*FRONT BUMPER LOWER	Dented	491.00 FL	*491.00 FL
16	1		*FRONT BUMPER LOWER LID	No such part	381.00 FL	*- FL
17	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	510.00 FL	*- FL
18	1		*FRONT BUMPER FOG LAMP HOLDER RH	Not Necessary	70.00 FL	*- FL
19	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	980.00 FL	*- FL
20	1		*FRONT BUMPER CENTER BRACKET	Not Necessary	150.00 FL	*- FL
21	1		*FRONT BUMPER GRILLE (RH)	Mtg Cracked	115.60 FL	*115.60 FL
22	1		*FRONT BUMPER UNDER COVER	Not Necessary	96.80 FL	*- FL
23	2		*FRONT BUMPER SENSOR	Not Necessary	432.00 FL	*- FL
24	2		*FRONT BUMPER SENSOR HOLDER	Not Necessary	40.00 FL	*- FL
25	1		*FRONT BUMPER SENSOR WIREHARNESS	Not Necessary	1,420.00 FL	*- FL
26	1		*FRONT BUMPER SPONGE	Not Necessary	390.00 FL	*- FL
27	1		*FRONT REINFORCEMENT BAR	Not Necessary	321.00 FL	*- FL
28	2		*FRONT REINFORCEMENT BAR BRACKET LH /RH	Not Necessary	320.00 FL	*- FL
29	1		*FRONT SUPPORT PANEL	Not Necessary	576.50 FL	*- FL
30	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	85.00 FL	*- FL
31	1		*FRONT BRACE PANEL	Not Necessary	101.00 FL	*- FL
32	1		*FRONT RADAR SENSOR ASSY	Not Necessary	2,950.00 FL	*- FL
33	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
37	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*COOLANT	Not Necessary	100.00 FS	*- FS
40	1		*FRONT LED LAMP RH	Not Necessary	200.00 FS	*- FS
41	1		*FRONT NO.PLATE & CASING	Not Necessary	200.00 FS	*- FS
					Sub Total (\$\$)	
					19,687.30	1,428.30
					- List Item Discount on L Items 20.00/20.00% (\$\$)	
					3,777.46	281.66
					Total Parts (\$\$)	
					15,909.84	1,146.64

F=Franchise part. S=SpcNett. L=ListItemDisc.

10/12/22, 9:41 AM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	600.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	450.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	400.00
4	TO TUFF COAT DAMAGED AREAS	New	200.00	0.00
5	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RNR RADIATOR ASSY & REFILL COOLANT FACILITATE REPAIRS	New	200.00	0.00
7	TO RNR FRONT BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	0.00
8	TO CALIBRATE FRONT RADAR SENSOR	New	1,000.00	0.00
9	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	600.00	0.00
Gross Labour Cost (\$\$)			7,150.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >