



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 5813H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BACKING ASSEMBLY	CRACKED	860.00	860.00
1	POLISHED BUMPER DRILL MOUNT	DENTED	1,710.00	1,710.00
1	BUMPER WITH CUTOUTS	DENTED	10,170.00	10,170.00
1	LOT WASHER, BOLT, BEZEL, GASKET RUBBER U-CHANNEL & SCREW	NECESSARY	200.00	200.00
1	DECKPLATE (ADDITIONAL)	BROKEN	1,270.00	1,270.00
	LESS 5% DISCOUNT		-	-710.50
			14,210.00	13,499.50
	<u>LABOUR</u>			
	TOWING, REPAIR AND SPRAY PAINTING OF FRONT LHS BODY PANEL.		1,800.00	1,710.00
	LABOUR CHARGE FOR THE FOLLOWING: REMOVAL OF DAMAGED FRONT ASSEMBLY AND INSPECT VEHICLE FOR ANY FURTHER DAMAGES. PREPARATION OF EQUIPMENT, CLEANING ETC. TO DISMANTLE AND INSTALL THE ABOVE SPARE PARTS ETC. REALIGN ALL REPLACEMENT ASSEMBLY. CARRY OUT FUNCTIONAL TEST POST COMPLETION OF WORK. (2 MEN X 8 MAN-HOURS X 3 DAYS X \$40)		1,920.00	1,920.00
			3,720.00	3,630.00
	GRAND TOTAL		17,930.00	17,129.50
	RECOMMENDED COST OF REPAIRS			17,129.50
	LESS EXCESS			-1,500.00
	NETT LIABILITY			15,629.50

Report Ref No. CS/FCI22004683/Vny3e2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.