

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22004687/GTY3N2**Date:** 13/06/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000792	
Claimant Vehicle No :	SHC2142A	Insured Vehicle No :	SMM2539C	
Date of Loss:	16/05/2022	Nature of Claim:	TP	Claim No: M2202453

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2142A	Engine No:	2ZR2B82915
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Chassis No:	JTDKB3FU403077645
Reg. Date:	06/12/2018 (Man. Year: 2018)	Odometer:	465673 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,558.62	541.17	1,017.45	65.28
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,120.00	640.00	480.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,689.62	1,192.17	1,497.45	55.68
Approved Total (Overridden) (S\$)		950.00		
(S\$)	2,689.62	950.00	1,739.62	64.68
+ GST 7.00/7.00% (S\$)	188.27	66.50	121.77	64.68
Nett Amount (S\$)	2,877.89	1,016.50	1,861.39	64.68

INSPECTION

Date of Assignment:	18/05/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	19/05/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2022)
Parts:	144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2142A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Repair	503.04 FL	-	*- FL
2	1		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	-	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	94.80 FL	-	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	94.80 FL	-	*- FL
5	1		*REAR BUMPER TOWING COVER	Not Necessary	82.70 FL	-	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	-	*- FL
7	1		*REAR BUMPER LOWER COVER	Deformed	654.90 FL	-	*654.90 FL
8	1		*REAR BUMPER ADVERTISEMENT STICKER	Necessary	50.00 F	-	*50.00 FS
9	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 F	-	*- FS
					Sub Total (\$\$)	2,016.26	704.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	457.64	163.73
					Total Parts (\$\$)	1,558.62	541.17

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/ REFIX REVERSE SENSOR	New	60.00	40.00
4	TUFF KOTE	New	60.00	0.00
Gross Labour Cost (\$\$)			1,120.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >