

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22004688/GYA3Q2**Date:** 16/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0001098_01

Claimant Vehicle No : SHC2783A **Insured Vehicle No :** GBE6758H

Date of Loss: 16/05/2022 Nature of Claim: TP Claim No: MCV2022D0002478

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC2783A**
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU402403
 Reg. Date: 07/11/2019 (Man. Year: 2019) Chassis No: KMHCB851CVLU188094
 Colour: Blue Odometer: 0 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,003.12	946.12	1,057.00	52.77
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	640.00	180.00	21.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,834.12	1,597.12	1,237.00	43.65
+ GST 7.00/7.00% (S\$)	198.39	111.80	86.59	43.65
Nett Amount (S\$)	3,032.51	1,708.92	1,323.59	43.65
+ Loss of Use (3.0 x S\$40.00/day) (S\$)		120.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,206.49		

INSPECTION

Date of Assignment: 18/05/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
 Date Inspected: 18/05/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2023)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2783A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRKT RH/LH	Not Necessary	276.20 FL	*- FL
4	1		*REAR BUMPER CENTRE MOULDING	Cut	451.25 FL	*451.25 FL
5	1		*REAR BUMPER LOWER MOULDING	Not Necessary	155.00 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR FOGLAMP	Not Necessary	201.50 FL	*- FL
8	1		*REVERSE SENSORS	Not Necessary	180.00 F	*- F
9	1		*REAR NO.PLATE WITH TRIM COVER	Not Necessary	55.00 F	*- F
10	2		*REAR FENDER ADVERTISEMEMT STICKER RH/LH	Necessary	200.00 F	*200.00 F
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	2,395.15 1,132.65
					- List Item Discount on L Items 20.00/20.00% (S\$)	392.03 186.53
					Total Parts (S\$)	2,003.12 946.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	40.00
Gross Labour Cost (\$\$)			820.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >