

PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE 510607

BUSINESS REGN. No. 53193457L

Email: willybit@gmail.com / Mobile: 96699986

VEHICLE DAMAGE INSPECTION REPORT

Mr. Lim Zheng Sen
Block 111 Gangsa Road #08-83
Singapore 670111

Our Ref : PA/FBL1938/0322/tpw
Date : 18 April 2022

REFERENCES

Claim Type	: Third Party	Date of Accident	: 16 March 2022
Vehicle No	: FBL 1938 B	Date of Assignment	: 22 March 2022
Make	: Kawasaki	Date of Inspection	: 22 March 2022
Model	: Z800 ABS M	Date of Re-inspection	: 04 & 14 April 2022
Registration Date	: 18 July 2016	COE Expiry	: 17 July 2026
Color	: Green	Chassis No	: JKBZR800ABDA15527
Odometer	: Battery flat	Engine No	: Blocked

TYRE CONDITION

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Michelin	120/70-17	5mm
Rear	Michelin	180/55-17	6mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and right sides.
Please refer to photographs and assessment of repairs for details
Enclosed (64) photographs depicting damages and after repaired

INSPECTION AND ADJUSTMENT

Original Quotation : \$6,236.32 Revised Assessment \$4,500.00 Lump sum

Survey conducted at Ong Motor Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
Five (5) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Note: The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock
reconditioned parts whichever is possible

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBL 1938 B

Our Ref: PA/FBL1938/0322/tpw

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

S/N	Description/Material	Qty	Condition	Original Quotation	Revised Quotation
1	Visor (meter cover)	1 pc	Cracked	163.90	163.90
2	Handle bar	1 pc	Bent	192.70	192.70
3	Handle bar balance	1 set	Grazed	80.00	80.00
4	Mirror assy @ \$103.90/-	2 pcs	Grazed/bent	207.80	207.80
5	Brake lever	1 pc	Bent	88.80	88.80
6	Front headlamp cowling	1 pc	Cracked	248.80	248.80
7	Front headlamp side cowling @ \$92.70/-	2 pcs	Cut	185.40	185.40
8	Front fork assy LH & RH @ \$1055.20/-	2 pcs	Bent	2,110.40	2,110.40
9	Front fender	1 pc	Cracked	227.80	227.80
10	Fuel tank side cowling RH	1 pc	Cut/grazed	183.20	183.20
				3,688.80	3,688.80
List price less discount 10%				368.88	368.88
				3,319.92	3,319.92

Special nett item

11	Steering cone & bearing	1 set	Necessary	240.00	120.00
12	Cowling side decal	1 pc	Necessary	60.00	60.00
13	Front wheel slider	1 set	Cut	150.00	120.00
14	Exhaust muffler protector clip	1 pc	Grazed	96.40	96.40
15	Rear aluminium Box	1 pc	Cut	750.00	650.00
16	Rear Box rack with base	1 pc	Bent	350.00	280.00
				1,646.40	1,326.40

Labour

Front wheel rim balance	120.00	80.00
Repair steering stem & align	200.00	150.00
Align body frame	450.00	350.00
To remove & replace damage parts	500.00	400.00
	1,270.00	980.00

Total parts & labour concluded	<u>6,236.32</u>	<u>5,626.32</u>
--------------------------------	-----------------	-----------------

Lump sum repair adjustment		<u>4,500.00</u>
----------------------------	--	-----------------

PRUDENT ADJUSTORS SERVICES

Vehicle No: FBL 1938 B

Our Ref: PA/FBL1938/0322/tpw

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.



Prudent Adjustors Services
Bok Jee Tan