



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22002583/Rvy3e2-1 Date: 02/06/2022 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GW 1883H	Veh. Inspected	SLZ 4929R	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/025567	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	18/05/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA CERATO K3 1.6A SUNROOF	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KNAFZ411MJ5761577	Colour	BROWN	
Odometer	61112 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/03/2022	Inspection Date	22/03/2022	
Survey held at	60 JALAN LAM HUAT #02-28 CARROS CENTRE			
Repairer	LONG VIEW MOTOR WORKS			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	