

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22004689/EYA3Q2**Date:** 12/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0000851_01

Claimant Vehicle No : GBG3700H **Insured Vehicle No :** GBE7349Z

Date of Loss: 07/04/2022 Nature of Claim: TP Claim No: MCV2022D0001878

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG3700H**
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2733002
 Reg. Date: 26/07/2017 (Man. Year: 2017) Chassis No: JTFAT35Y80K208554
 Colour: Blue Odometer: 160956 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: 4 mm Rear Left Side: 4 mm
 Front Right Side: 4 mm Rear Right Side: 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,576.56	2,133.52	1,443.04	40.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	950.00	700.00	42.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,226.56	3,083.52	2,143.04	41.00
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	5,226.56	2,450.00	2,776.56	53.12
+ GST 7.00/7.00% (S\$)	365.86	171.50	194.36	53.12
Nett Amount (S\$)	5,592.42	2,621.50	2,970.92	53.12
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,944.50		

INSPECTION

Date of Assignment: 17/05/2022

Date Inspected: 19/05/2022 Inspected At:

Shu Fatt Auto Works (HQ)
Block 1009 Bukit Merah Lane 3, #01-90
Singapore 159723

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Apr 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3700H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RT FRT HEADLIGHT	Cut	1,060.00 FL	*1,060.00 FL
2	1		*FRT BUMPER	Repair	748.90 FL	*- FL
3	1		*RT FRT DOOR	Dented	1,902.20 FL	*1,784.70 FL
4	1		*RT FRT DOOR RUBBER	Not Necessary	168.90 FL	*- FL
5	1		*RT FRT DOOR LOWER HINGE	Not Necessary	79.60 FL	*- FL
6	1		*RT FRT DOOR ARCH RUBBER	Not Necessary	83.20 FL	*- FL
7	1		*RT FRT STEP GARNISH	Not Necessary	321.00 FL	*- FL
8	1		*RT FRT STEP GARNISH PANEL	Not Necessary	70.90 FL	*- FL
9	1		*SET RT FRT STEP GARNISH CLIPS	Not Necessary	36.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					4,470.70	2,844.70
- List Item Discount on L Items 20.00/25.00% (S\$)					894.14	711.18
Total Parts (S\$)					3,576.56	2,133.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK ,STRAIGHTEN FRT INNER PANEL ,FRT LOWER PANEL ,FRT SIDE PANEL ,RT FRT PILLAR ,RT FRT ARCH PANEL ,RT FRT STEP INNER PANEL ,RENEW FRT LIGHT ,FRT BUMPER ,RT FRT DOOR ,STEP GARNISH AND ASSEMBLY	New	750.00	400.00
2	TO RESPRAY DAMAGED PARTS	New	750.00	500.00
3	TO REMOVE ,REPLACE ,TRANSFER RT FRT DOOR GLASS ,REGULATOR ,GLASS MOTOR ,INNER HANDLE ,OUTER HANDLE ,INNER LOCK ,OUTER LOCK RUBBERS MOULDINGS ,BOARDS AND ASSEMBLY	New	150.00	50.00
Gross Labour Cost (S\$)			1,650.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >