

Vehicle Damage Assessment Report for [GBG3700H]

Estimate Created: 26/08/2022 10:13 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 26/04/2023 01:20 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number	MCV2022D0001878
Claim Type	TP		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Toyota	Model	Hilux
Engine Type	1KDFTV		
License Plate Number	GBG3700H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$2,450.00 WITH 4 WORKING DAYS

Insurlogic 5 (26/04/2023 01:18)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
RT FRT HEADLIGHT		1	1060.00	-25.00 %	795.00
RT FRONT DOOR		1	1784.70	-25.00 %	1,338.53

Parts Subtotal 2,133.53

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
TO KNOCK STRAIGHTEN FRONT INNER PANEL TRT LOWER PANE; FRONT SIDE PANEL FRONT PALLAR, RT FRONT ARCH PANE; RT FRONT STEP INNER PANE; RENEW FRONT HIGHT FRONT BUMPER RT DOOR STEP GAMISHAND ASSEMBLY	RnR	400.00	0.00 %	400.00
TO RESPRAY DAMAGED PANEL	RnR	500.00	0.00 %	500.00
TO REMOVE REPLACE TRANSFER RT FRONT DOOR GLASS REGULATOR GLASS MOTOR INNER HANDLE CUTER HANDLE INNER LOCK CUTER LOCK RUBBERS MOULDINPS BRANDS AND ASSEMBLY	RnR	50.00	0.00 %	50.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 950.00

Paint Labor Subtotal 0.00

Labor Subtotal 950.00

Summary

Repair Cost 3,083.53

Discount(20 %) (616.71)

2,466.82

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 2,466.82