

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004691/AVCE2**Date:** 18/11/2022**REFERENCE**

Insured/Claimant: CHAN ZHICONG DAMIEN (ZENG ZHICONG DAMIEN) Policy No: 2070051983-01

Date of Loss: 12/05/2022

Nature of Claim: OD

Claim No: 4938005159SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS8799Y	Engine No:	CVK087542
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Chassis No:	WAUZZZF48KA114978
Reg. Date:	19/03/2020 (Man. Year: 2019)	Odometer:	23543 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$151,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,228.00	13,538.48	20,689.52	60.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,882.00	6,262.00	6,620.00	51.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,110.00	19,800.48	27,309.52	57.97
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	46,010.00	18,700.48	27,309.52	59.36
+ GST 7.00/7.00% (S\$)	3,220.70	1,309.03	1,911.67	59.36
Nett Amount (S\$)	49,230.70	20,009.51	29,221.19	59.36

INSPECTION

Date of Assignment: 19/05/2022

Date Inspected: 18/05/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	254.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	144.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,478.00 FS	*1,182.40 FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	302.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
11	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	508.00 FS	*- FS
12	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	82.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Cracked	143.00 FS	*114.00 FS
14	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
15	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
16	1		*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	154.00 FS	*122.80 FS
17	2		*FRONT BUMPER SUPPORT - LH / RH	Deformed	64.00 FS	*51.04 FS
18	4		*FRONT BUMPER POP RIVET	Necessary	4.00 FS	*2.88 FS
19	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	530.00 FS	*- FS
20	4		*FRONT BUMPER SEAL RING	Not Necessary	10.00 FS	*- FS
21	2		*HORN - LH / RH	Not Necessary	273.00 FS	*- FS
22	2		*HORN BRACKET - LH / RH	Not Necessary	66.00 FS	*- FS
23	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
25	2		*BONNET HINGE - LH / RH	Not Necessary	680.00 FS	*- FS
26	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
27	2		*BONNET STRIKER - LH / RH	Not Necessary	112.00 FS	*- FS
28	2		*BONNET LOCK	Not Necessary	455.00 FS	*- FS
29	1		*BONNET BOWDEN CABLE - UPPER	Damaged	64.00 FS	*50.56 FS
30	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE - LOWER	Not Necessary	64.00 FS	*- FS
32	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
33	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	522.00 FS	*- FS
34	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	164.00 FS	*- FS
35	1		*HEADLIGHT - LH / RH	N/s cracked	16,588.00 FS	*6,635.20 FS
36	2		*LIFT CYLINDER - LH / RH	Not Necessary	462.00 FS	*- FS
37	2		*LIFT CYLINDER BRACKET - LH / RH	Not Necessary	14.00 FS	*- FS
38	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
39	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
40	1		*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
41	1		*A/C CONDENSER	Dented	683.00 FS	*546.00 FS
42	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
43	2		*RADIATOR AIR GUIDE OUTER - LH / RH	Not Necessary	64.00 FS	*- FS
44	2		*RADIATOR AIR GUIDE INNER - LH / RH	Deformed	28.00 FS	*21.76 FS
45	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
47	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
48	1		*SUNDRIES	Necessary	350.00 FS	*18.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **34,228.00** **13,538.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,400.00	780.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER, BONNET AND HINGES	New	2,500.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REPAIR LHS FRONT FENDER (Supplementary)	New	700.00	250.00
8	TO RESPRAY LHS FRONT FENDER (Supplementary)	New	1,050.00	550.00
9	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS. (Supplementary)	New	560.00	560.00
10	TO RESPRAY BOTH FRONT DOORS. (Supplementary)	New	1,100.00	1,100.00
Gross Labour Cost (\$\$)			12,882.00	6,262.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >