



# PRIORITY SERVICES

## INSURANCE LOSS ADJUSTERS AND MOTOR APPRAISERS

Block 779 Yishun Avenue 2 #01-1545 Singapore 760779  
Tel: 6293 4822 Fax: 6296 3283

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: TP-0171/04/19  
Date: 17/05/2019

#### REFERENCE

Handling Insurer: Sampo Insurance Singapore Pte. Ltd. Policy No: D18MTMC01005744  
Claimant Vehicle No: SLN5077E Insured Vehicle No: FBK4801Y  
Date of Loss: 10/04/2019 Nature of Claim: TP Claim No: CMTD1901877

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN5077E**  
Make & Model: SUBARU XV, 1.6 (A) Engine No: FB16Y453497  
Reg. Date: 06/05/2017 (Man. Year: 2016) Chassis No: JF1GP3KC5GG175477  
Colour: Pearl White Odometer: 60095 km  
Engine Capacity: 1600 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

#### CONDITION OF TYRES

Front Tyre Size: 225/55/R17 Rear Tyre Size: 225/55/R17  
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm  
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment: 16/04/2019  
Date Inspected: 17/04/2019 Inspected At: Ms Car Auto Pte Ltd (HQ)  
8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT  
Singapore 415875  
Estimated Period of Repair: 0.0 days

Adjuster: Lawrence Ng  
Surveyor

Manager: Sharon Kho  
Administrator

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**PRE-REPAIR SURVEY**

Date of Accident : 10-Apr-2019

Date and Time of Request : 16-Apr-2019 / 4.06pm

Date and Time of Inspection : 1) 17-Apr-2019 / 10.05am

2) 18-Apr-2019 / 9.15am (For dismantled items)

3) 22-Apr-2019 / 10.30am (For after repair)

**DOCUMENTS AVAILABLE AT TIME OF INSPECTION**

1)T/P SLN 5077 E Police Report

**VISUAL DAMAGES**

At the LH rear portion. (LH rear wheel was also affected)

Damages subject to consistency.

**REMARKS**

Despite our request, the repairer would not provide: -

1) Repairer estimate

Pre-Accident market value: About \$78,000.00.

PARF/COE Rebate: \$54,449.00 (COE expiry on 05-May-2027).

Estimated repair cost: About \$1,500.00.

Estimated period of repairs: About 3 working days.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2019)
<b>Parts:</b>	144	SUBARU XV 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	<b>Priority Services/SLN5077E/17/05/2019 10:51</b>	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

**Priority Services/SLN5077E/17/05/2019 10:51**. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

<b>Priority Services/SLN5077E/17/05/2019 10:51</b> . Not valid without Reference section.
---

**< END OF ESTIMATES >**