

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22004698/EVY3E2

Date: 01/06/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001803973		
Claimant Vehicle No :	SME8909X	Insured Vehicle No :	GBG4429K		
Date of Loss:	13/05/2022	Nature of Claim:	TP	Claim No:	274632

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME8909X	Engine No:	LEB5968726
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31268704
Reg. Date:	22/10/2018 (Man. Year: 2017)	Odometer:	286445 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,033.32	2,114.80	918.52	30.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,410.00	200.00	12.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,643.32	3,524.80	1,118.52	24.09
+ GST 7.00/7.00% (S\$)	325.03	246.74	78.29	24.09
Nett Amount (S\$)	4,968.35	3,771.54	1,196.81	24.09

INSPECTION

Date of Assignment:	19/05/2022	
Date Inspected:	19/05/2022	Inspected At: Prime Auto Claims Service Pte Ltd (HQ) 6 Benoi Place Singapore 629927
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME8909X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER LOWER GARNISH	Dented	985.00 FL	*762.00 FL
2	1		*LEFT REAR BUMPER	Crushed	245.00 FL	*180.00 FL
3	1		*REAR BUMPER LEFT REFLECTOR	Broken	189.00 FL	*141.00 FL
4	1		*TAILGATE	Dented	1,100.90 FL	*953.00 FL
5	1		*TAILGATE H EMBLEM	Not Necessary	38.00 FL	*- FL
6	1		*TAILGATE VEZEL EMBLEM	Necessary	60.00 FL	*60.00 FL
7	1		*TAILGATE HYBRID EMBLEM	Necessary	60.00 FL	*60.00 FL
8	1		*REAR END PANEL	Repair	520.00 FL	*- FL
9	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
10	1		*SET REVERSE SENSORS	Shorted	200.00 FS	*200.00 FS
11	1		*TUBE REAR GLASS SEALANT	Necessary	45.00 FS	*40.00 FS
12	1		*SET REAR GLASS MOULDING (4PCS)	Necessary	200.00 FS	*120.00 FS
					Sub Total (\$\$)	3,672.90 2,546.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	639.58 431.20
					Total Parts (\$\$)	3,033.32 2,114.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TUFF KOTE AFFECTED PORTION	New	50.00	30.00
2	TO TRANSFER TAILGATE TRIM BOARD, HANDLE, MECHANISM PARTS & ETC	New	60.00	30.00
3	TO REMOVE & REFIT REAR GLASS	New	120.00	120.00
4	TO REMOVE & REPLACE REVERSE SENSORS & REFIT REAR CAMERA, CHECK WIRING	New	80.00	30.00
5	TO KNOCK & REPAIR REAR END PANEL. REMOVE REAR BUMPER LOWER GARNISH, LEFT REAR BUMPER, TAILGATE & ETC. REPLACE THE ABOVE PARTS, ADJUST & ALIGN REAR BUMPER & TAILGATE	New	700.00	600.00
6	TO PUTTY RESPRAY PAINTING TAILGATES INLET & OUTE, REAR END PANEL & LEFT REAR BUMPER. TO POLISH	New	600.00	600.00
Gross Labour Cost (\$\$)			1,610.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >