



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFC 9383Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CRACKED	1,396.00	1,026.50
14	FRONT BUMPER CLIPS @\$4.50	NECESSARY	63.00	63.00
1	FRONT BUMPER BRACKET RH	SERVICEABLE	145.00	-
1	FRONT BUMPER CORNER RETAINER RH	CRACKED	95.00	95.00
6	FRONT BUMPER TOP RIVETS @\$6.00	NOT NECESSARY	36.00	-
1	HEADLAMP RH (HID)	MTG CRACKED	2,970.00	2,970.00
1	WIPER TANK	SERVICEABLE	185.00	-
1	WIPER TANK MOTOR	SERVICEABLE	146.00	-
1	FRONT FENDER RH	BENT	462.00	462.00
1	FRONT FENDER SHIELD RH	CRACKED	250.00	148.10
8	FRONT FENDER SHIELD CLIPS @\$4.80	NOT NECESSARY	38.40	-
	LESS 20% DISCOUNT		-1,157.28	-952.92
			4,629.12	3,811.68
LABOUR				
	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP.		30.00	20.00
	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED/REPAIR PANEL.		50.00	30.00
	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF FRONT FENDER INNER PANEL & PART REPLACEMENT.		600.00	400.00
	TO RESPRAY AFFECTED AREAS .		580.00	400.00
			1,260.00	850.00
GRAND TOTAL			5,889.12	4,661.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,750.00

Report Ref No. CS/FCI22004700/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.