



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 5097H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	667.20	-
10	REAR BUMPER CLIPS	NOT NECESSARY	50.00	-
2	TAILLAMP RH / LH	CUT	494.60	247.30
1	TAILGATE	DENTED	1,986.70	1,986.70
1	TAILGATE REAR VIEW MIRROR	BROKEN	220.50	220.50
1	TAILGATE LOCK	NOT NECESSARY	297.50	-
1	TAILGATE WEATHERSTRIPE	NOT NECESSARY	154.50	-
1	END PANEL (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-387.10	-245.45
			3,483.90	2,209.05
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	NOT NECESSARY	220.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	70KM/HR (SN)	NECESSARY	10.00	10.00
1	8 PAX STICKER (SN)	NECESSARY	10.00	10.00
1	REAR ADVERTISEMENT STICKER (SN)	NECESSARY	400.00	400.00
			690.00	460.00
<u>LABOUR</u>				
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		800.00	300.00
	TO RESPRAY AFFECTED AREAS.		800.00	400.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		120.00	120.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	30.00
			1,750.00	850.00
GRAND TOTAL			5,923.90	3,519.05



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00
---	--	--	-----------------

Report Ref No. CS/UOI22004705/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.