

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited  
10 Eunus Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS22004708/KTY3E2

**Date:** 17/06/2022

### REFERENCE

Insured/Claimant:	BIS MOTORING PTE. LTD.	Policy No:	MCF22A00000100	
Date of Loss:	07/05/2022	Nature of Claim:	OD	Claim No: DMCF2200051H

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC7322E	Engine No:	D4FDJH551962
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7205823
Reg. Date:	19/07/2018 (Man. Year: 2018)	Odometer:	357966 km
Colour:	Metallic Pearl White		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	DURATURN 9 mm	Rear Left Side:	DURATURN 7 mm
Front Right Side:	DURATURN 9 mm	Rear Right Side:	DURATURN 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,662.00	2,662.00	0.00	0.00
Miscellaneous Items	85.00	85.00	0.00	0.00
Labour	1,990.00	960.00	1,030.00	51.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,737.00</b>	<b>3,707.00</b>	<b>1,030.00</b>	<b>21.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,950.00</b>		
<b>- Excess (S\$)</b>	2,000.00	2,000.00	0.00	0.00
<b>(S\$)</b>	2,737.00	950.00	1,787.00	65.29
<b>+ GST 7.00/7.00% (S\$)</b>	191.59	66.50	125.09	65.29
<b>Nett Amount (S\$)</b>	<b>2,928.59</b>	<b>1,016.50</b>	<b>1,912.09</b>	<b>65.29</b>

### INSPECTION

Date of Assignment:	19/05/2022	Present Location:	Munich Autocare Pte Ltd (HQ)
Date Inspected:	19/05/2022	Inspected At:	Munich Autocare Pte Ltd (HQ) 60 Jalan Lam Huat, #07-43 Singapore 737869
Estimated Period of Repair:	3.0 days		

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2022)
<b>Parts:</b>	M1-MPV	KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMC7322E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*WIPER TANKS WITH MOTOR</b> (WCP)	Dented	35.00 F	*35.00 F
2	1		<b>*FRONT SUPPORT PANEL</b> (WCP)	Bent	260.00 F	*260.00 F
3	1		<b>*FRONT ENGINE COVER</b> (WCP)	Cracked	95.00 F	*95.00 F
4	1		<b>*A/COND PIPE</b> (WCP)	Bent	250.00 F	*250.00 F
5	1		<b>*ENGINE OIL PAN</b> (WCP)	Cracked	580.00 F	*580.00 F
6	1		<b>*FRONT CROSSMEMBER</b> (WCP)	Bent	780.00 F	*780.00 F
<b><u>Supplementary #1</u></b>						
7	1		<b>*RADIATOR ASSY</b> (WCP)	Housing Cracked	420.00 F	*420.00 F

Sub Total (\$\$)	2,420.00	2,420.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	242.00	242.00
Total Parts (\$\$)	2,662.00	2,662.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	ENGINE OIL 5L (NECESSARY)	60.00	60.00
2	1	ENGINE UNDER COVER CLIPS (NECESSARY)	25.00	25.00
<b>Sub Total (\$\$)</b>			<b>85.00</b>	<b>85.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION,BUMPER, SUPPORT PANEL,ENGINE OIL PAN AND DAMAGE AREA	New	500.00	450.00
2	TO CHECK ALL WIRING FOR OPERATION AND OIL PANT SENSOR WIRE AND PARKING SENSOR FOR OPERATION	New	120.00	50.00
3	TO REMOVE/INSTALL A/COND CONDENSOR, RADIATOR COOLING SYSTEM TO REPLACE FRONT SUPPOORT PANEL AND DAMAGE AREA	New	180.00	100.00
4	TO CONDUCT RE-PROGRAME AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	250.00	0.00
5	TO REFILL A/COND GAS	New	120.00	100.00
6	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00	60.00
7	TO REMOVE AND INSTALL FRONT CROSSMEMBER AND CONTROL SYSTEM TO FACLLITATE THE WORK	New	200.00	200.00
8	TO RESPRAY FRONT PORTION,FRONT BUMPER AND POLISH DAMAGE AREAS	New	500.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,990.00</b>	<b>960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >