

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004713/DQY3N2**Date:** 17/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00218902100

Claimant Vehicle No : SMN1275P **Insured Vehicle No :** SLZ3272H

Date of Loss: 15/05/2022 Nature of Claim: TP Claim No: SNM22D203363/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN1275P**

Make & Model: HONDA CITY, 1.5 (A) Engine No: L15Z16930586

Reg. Date: 25/07/2019 (Man. Year: 2019) Chassis No: MRHGM6660LT000022

Colour: Silver Odometer: 8440 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R16 Rear Tyre Size: 185/55R16

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,366.16	2,779.12	21,587.04	88.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,570.00	1,580.00	3,990.00	71.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	29,936.16	4,359.12	25,577.04	85.44
Approved Total (Overridden) (\$\$)		3,400.00		
(\$\$)	29,936.16	3,400.00	26,536.16	88.64
+ GST 7.00/7.00% (\$\$)	2,095.53	238.00	1,857.53	88.64
Nett Amount (\$\$)	32,031.69	3,638.00	28,393.69	88.64

INSPECTION

Date of Assignment: 19/05/2022

Date Inspected: 20/05/2022 Inspected At: C.S. Ong Auto Pte Ltd (AMK)
10 Ang Mo Kio Industrial Park 2A, #02-16, AMK
Auto Point
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2022)
Parts:	143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN1275P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted/Mounting Cracked	901.00 FL	*655.00 FL
2	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	250.00 FL	*- FL
3	1		*FRONT FENDER RH	Dented	910.00 FL	*566.00 FL
4	1		*FRONT FENDER INNER SHIELD RH	Serviceable	201.00 FL	*- FL
5	1		*FRONT WHEEL BEARING RH	Damaged	596.00 FL	*255.30 FL
6	1		*FRONT WHEEL BEARING HUB RH	Not Necessary	698.20 FL	*- FL
7	1		*FRONT KNUCKLE ARM RH	Distorted	1,584.00 FL	*455.00 FL
8	1		*FRONT LOWER ARM RH	Distorted	733.00 FL	*439.80 FL
9	1		*FRONT ABSORBER RH	Distorted	834.00 FL	*452.80 FL
10	1		*FRONT STABILIZER LINK RH	Not Necessary	518.00 FL	*- FL
11	1		*FRONT STABILIZER BAR	Not Necessary	510.00 FL	*- FL
12	1		*FRONT TIE ROD RH	Not Necessary	620.00 FL	*- FL
13	1		*FRONT TIE ROD END RH	Not Necessary	882.00 FL	*- FL
14	1		*STEERING RACK & PINION ASSY	Not Necessary	2,890.00 FL	*- FL
15	1		*DRIVE SHAFT RH	Not Necessary	3,784.00 FL	*- FL
16	1		*SIDE MIRROR ASSY RH	Not Necessary	1,456.00 FL	*- FL
17	1		*SIDE MIRROR ASSY GARNISH RH	Not Necessary	384.00 FL	*- FL
18	1		*FRONT DOOR RH	Repair	2,560.00 FL	*- FL
19	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	310.00 FL	*- FL
20	1		*FRONT DOOR BLACK STICKER RH	Not Necessary	194.00 FL	*- FL
21	1		*FRONT DOOR HANDLE RH	Not Necessary	198.00 FL	*- FL
22	1		*FRONT DOOR LOCK RH	Not Necessary	432.00 FL	*- FL
23	1		*FRONT DOOR WEATHER STRIP INNER RH	Not Necessary	493.00 FL	*- FL
24	1		*FRONT DOOR WEATHER STRIP OUTER RH	Not Necessary	480.00 FL	*- FL
25	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	854.00 FL	*- FL
26	1		*FRONT DOOR WINDOW MOTOR RH	Not Necessary	954.00 FL	*- FL
27	1		*FRONT DOOR WINDOW REGULATOR RH	Not Necessary	690.00 FL	*- FL
28	1		*ROCKER PANEL RH	Repair	1,654.00 FL	*- FL
29	1		*SPORT RIM	Cut	2,000.00 FS	*500.00 FS
30	1		*TYRE	Serviceable	800.00 FS	*- FS
31	1		*FRONT FENDER QUARTER GARNISH CLIPS	Serviceable	50.00 FS	*- FS
32	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	29,680.20	3,343.90
- List Item Discount on L Items 20.00/20.00% (\$)	5,314.04	564.78
Total Parts (\$)	24,366.16	2,779.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	500.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	800.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
4	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	180.00
5	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	120.00	60.00
6	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	0.00
7	TO CHECK & RE-FIX ALL ELECTRICAL WIRING	New	200.00	0.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			5,570.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >