

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004714/AQY3E2

Date: 05/08/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00162702100
Claimant Vehicle No: SKU9247E Insured Vehicle No: SLM3362A
Date of Loss: 14/05/2022 Nature of Claim: TP Claim No: SNM22D203317/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU9247E**
Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGFH784134
Reg. Date: 24/08/2015 (Man. Year: 2015) Chassis No: KNAFZ411MF5470120
Colour: White Odometer: 133759 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,177.71	14,747.41	7,430.30	33.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,990.00	3,980.00	2,010.00	33.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,167.71	18,727.41	9,440.30	33.51
Approved Total (Overridden) (S\$)		14,950.00		
(S\$)	28,167.71	14,950.00	13,217.71	46.93
+ GST 7.00/7.00% (S\$)	1,971.74	1,046.50	925.24	46.93
Nett Amount (S\$)	30,139.45	15,996.50	14,142.95	46.93

INSPECTION

Date of Assignment: 19/05/2022
Date Inspected: 19/05/2022 Inspected At: Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717
Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2022)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU9247E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE GARNISH	Deformed	68.90 FL	*68.90 FL
2	1		*FRONT BUMPER	Deformed	639.00 FL	*639.00 FL
3	2		*FRONT BUMPER SIDE HOLDER - LH & RH	Necessary	52.00 FL	*52.00 FL
4	1		*FRONT BUMPER SPONGE	Cracked	145.00 FL	*145.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	410.00 FL	*410.00 FL
6	2		*FRONT BUMPER FOG LAMP - LH & RH	Not Necessary	410.00 FL	*- FL
7	2		*FRONT BUMPER FOG LAMP COVER - LH & RH	Not Necessary	90.00 FL	*- FL
8	1		*FRONT BUMPER TOW COVER	Not Necessary	23.00 FL	*- FL
9	2		*FRONT BUMPER SENSOR - LH / RH	Not Necessary	510.00 FL	*- FL
10	2		*FRONT BUMPER SENSOR HOLDER - LH & RH	Necessary	56.00 FL	*56.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Cracked	169.00 FL	*169.00 FL
12	1		*FRONT BUMPER LOWER BEAM	Not Necessary	138.00 FL	*- FL
13	1		*FRONT BUMPER LOGO	Necessary	51.00 FL	*51.00 FL
14	1		*FRONT GRILLE	Cracked	256.00 FL	*256.00 FL
15	1		*FRONT GRILLE MOULDING	Cracked	136.00 FL	*136.00 FL
16	2		*HEADLAMP - LH & RH	Cracked	4,736.00 FL	*4,736.00 FL
17	1		*BONNET	Repair	877.00 FL	*- FL
18	1		*BONNET LOCK	Not Necessary	65.00 FL	*- FL
19	1		*FRONT SUPPORT PANEL	Not Necessary	766.00 FL	*- FL
20	1		*FRONT SUPPORT PANEL TOP COVER	Cracked	235.00 FL	*235.00 FL
21	1		*AIRCON CONDENSER	Dented	774.00 FL	*774.00 FL
22	2		*AIRCON CONDENSER SIDE GUIDE - LH & RH	Not Necessary	70.00 FL	*- FL
23	1		*RADIATOR	Dented	692.00 FL	*692.00 FL
24	1		*RADIATOR FAN COWLING	Not Necessary	205.00 FL	*- FL
25	1		*REAR BUMPER	Distorted	698.00 FL	*698.00 FL
26	2		*REAR BUMPER SIDE HOLDER - LH / RH	Necessary	64.00 FL	*64.00 FL
27	1		*REAR BUMPER REFLECTOR - LH & RH	O/S Cracked	152.00 FL	*76.00 FL
28	1		*REAR BUMPER LOWER GARNISH	Distorted	296.00 FL	*296.00 FL
29	1		*REAR BUMPER REINFORCEMENT	Distorted	380.00 FL	*380.00 FL
30	1		*REAR BUMPER REINFORCEMENT STAY - LH & RH	O/S Distorted	136.00 FL	*67.00 FL
31	1		*REAR BUMPER INNER SIDE COVER - RH	Damaged	69.00 FL	*69.00 FL
32	1		*REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	1,000.00 FL	*500.00 FL
33	4		*REVERSE SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
34	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	279.00 FL	*- FL
35	1		*REAR END PANEL	Distorted	375.00 FL	*375.00 FL
36	1		*REAR END PANEL TOP GARNISH	Cracked	153.00 FL	*153.00 FL
37	1		*TAILLAMP - LH & RH	O/S Cracked	1,584.00 FL	*792.00 FL
38	1		*TAILLAMP PANEL - LH & RH	O/S Dented	454.00 FL	*227.00 FL
39	1		*BOOTLID	Dented	894.00 FL	*894.00 FL
40	1		*BOOTLID LOCK	Damaged	246.00 FL	*246.00 FL
41	1		*BOOTLID WEATHERSTRIPE	Cut	154.00 FL	*154.00 FL
42	1		*BOOTLID REFLECTOR - LH & RH	O/S Cracked	1,392.00 FL	*696.00 FL
43	1		*BOOTLID HINGE - LH & RH	Not Necessary	136.00 FL	*- FL
44	1		*KIA LOGO	Necessary	55.00 FL	*55.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FORTE WORDING	Necessary	52.00 FL	*52.00 FL
46	1		*K3 EMBLEM	Necessary	45.00 FL	*45.00 FL
47	1		*CYCLE AND CARRIAGE EMBLEM	Necessary	38.00 FL	*38.00 FL
48	1		*REAR FENDER INNER TRIM - RH	Deformed	278.00 FL	*278.00 FL
49	1		*SPARE TYRE PANEL	Repair	866.00 FL	*- FL
50	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	215.00 FL	*- FL
51	1		*REAR EXHAUST PIPE	Repair	757.00 FL	*- FL
52	1		*FRONT NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
53	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
54	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
55	1		*FRONT BUMPER LOWER SPOILER	Deformed	800.00 FS	*600.00 FS
56	1		*FRONT BUMPER LOWER GRILLE CARBON FIBRE STICKER	Necessary	80.00 FS	*60.00 FS
57	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
58	1		*FRONT GRILLE MOULDING CARBON FIBRE STICKER	Necessary	150.00 FS	*60.00 FS
59	1		*SET FRONT SUPPORT PANEL TOP COVER CLIPS	Necessary	20.00 FS	*20.00 FS
60	1		*SET AIRCON CONDENSER SIDE GUIDE CLIPS	Not Necessary	20.00 FS	*- FS
61	1		*COOLANT	Necessary	50.00 FS	*50.00 FS
62	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
63	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
64	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
65	2		*REAR BUMPER SIDE LOWER GARNISH - LH & RH	Necessary	400.00 FS	*400.00 FS
66	1		*SET REAR BUMPER INNER SIDE COVER CLIPS	Necessary	10.00 FS	*10.00 FS
67	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	10.00 FS	*10.00 FS
68	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
69	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
70	1		*REAR EXHAUST CHROME PIPE	Dented	150.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	24,421.90	16,214.90
- List Item Discount on L Items 10.00/10.00% (S\$)	2,244.19	1,467.49
Total Parts (S\$)	22,177.71	14,747.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING OUT FRONT & REAR PORTION & RENEW ABOVE PARTS	New	2,500.00	1,800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	2,200.00	1,600.00
3	TO CHECK WIRING	New	100.00	60.00
4	TO REMOVE CONDENSER & TOP-UP AIRCON GAS	New	120.00	60.00
5	TO REMOVE RADIATOR & TOP-UP COOLANT	New	120.00	60.00
6	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
7	TO REMOVE REVERSE SENSOR	New	100.00	60.00
8	TO SPRAY TUFF COAT	New	200.00	80.00
9	TO REMOVE UPHOLSTERY	New	150.00	80.00
10	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
11	TO REMOVE REAR CAMERA	New	100.00	50.00
12	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			5,990.00	3,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >