

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004715/RNY3M4**Date:** 05/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00012412100

Claimant Vehicle No : SNF642A **Insured Vehicle No :** CB6386B

Date of Loss: 13/05/2022 Nature of Claim: TP Claim No: SNM22D203330/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF642A**

Make & Model: TOYOTA YARIS CROSS, 1.5 XB CVT (A) Engine No: M15AY318561

Reg. Date: 28/04/2022 (Man. Year: 2022) Chassis No: MXPB103016645

Colour: Blue Odometer: 1577 km

Engine Capacity: 1490 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,629.96	5,583.04	3,046.92	35.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	1,620.00	1,530.00	48.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,779.96	7,203.04	4,576.92	38.85
Approved Total (Overridden) (\$\$)		5,750.00		
Nett Amount (\$\$)	11,779.96	5,750.00	6,029.96	51.19

INSPECTION

Date of Assignment: 19/05/2022

Date Inspected: 19/05/2022 Inspected At: JC AUTO WORKS (HQ)
NO. 60 JALAN LAM HUAT #02-23/24 CARROS
CENTRE
Singapore 737869

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2022)
Parts:	M1-SUV	TOYOTA YARIS CROSS 1.5 XB CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF642A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,187.40 FL	*1,187.40 FL
2	1		*FRONT BUMPER LOGO EMBLEM	Necessary	84.24 FL	*84.24 FL
3	1		*FRONT BUMPER LOWER	Not Necessary	377.52 FL	*- FL
4	2		*FRONT BUMPER RETAINER LH & RH	Not Necessary	184.40 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Cracked	101.88 FL	*101.88 FL
6	1		*FRONT REINFORCEMENT	Not Necessary	423.72 FL	*- FL
7	1		*FRONT NUMBER PLATE GARNISH	Cracked	102.36 FL	*102.36 FL
8	1		*RADIATOR GRILLE	Not Necessary	484.20 FL	*- FL
9	1		*RADIATOR UPPER AIR GUIDE	Not Necessary	149.88 FL	*- FL
10	2		*FRONT HEADLAMP ASSY LH & RH	Cracked	3,126.62 FL	*3,126.62 FL
11	2		*FRONT HEADLAMP BRACKET LH & RH	Not Necessary	246.96 FL	*- FL
12	1		*FRONT FENDER LH & RH	N/s Bent / O/s Repair	1,821.12 FL	*910.56 FL
13	2		*FRONT FENDER ARCH GARNISH LH & RH	Deformed	535.92 FL	*535.92 FL
14	1		*FRONT SUPPORT PANEL ASSY	Not Necessary	395.76 FL	*- FL
15	2		*FRONT END PANEL MOUNTING BRACKET SUB ASSY LH & RH	Bent	150.24 FL	*150.24 FL
16	1		*BONNET	Bent	1,104.84 FL	*1,104.84 FL
17	2		*BONNET HINGE LH & RH	Not Necessary	183.84 FL	*- FL
18	1		*BONNET INSULATOR	Not Necessary	366.80 FL	*- FL
19	1		*BONNET LOCK	Not Necessary	118.92 FL	*- FL
20	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
21	1		*SET FRONT NUMBER PLATE	Cracked	50.00 FS	*35.00 FS
22	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
23	2		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	100.00 FS	*- FS
24	1		*SET BONNET INSULATOR CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,416.62	7,409.06
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,786.66	1,826.02
Total Parts (\$\$)	8,629.96	5,583.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE & PANEL BEATING AFFECTED PARTS	New	1,200.00	600.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	800.00
3	TO APPLY ANTI-RUST ON AFFECTED AREAS	New	200.00	40.00
4	TO REMOVE/REPLACE/REFIT RADIATOR, AIRCON SYSTEM & REFILL GAS	New	200.00	0.00
5	TO CHECK WIRING	New	50.00	30.00
6	TO PERFORM SYSTEM DIAGNOSTIC & RESET ECU	New	300.00	150.00
Gross Labour Cost (\$)			3,150.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >