

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004716/VNY3E2

Date: 26/08/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00241322100		
Claimant Vehicle No :	SLB6062D	Insured Vehicle No :	SKQ8352L		
Date of Loss:	17/05/2022	Nature of Claim:	TP	Claim No:	SNM22D203367/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB6062D	Engine No:	2ARU309513
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	MR053AK5004010807
Reg. Date:	15/04/2016 (Man. Year: 2016)	Odometer:	99456 km
Colour:	Silver		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,013.07	5,593.62	9,419.45	62.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	2,580.00	1,570.00	37.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,163.07	8,173.62	10,989.45	57.35
Approved Total (Overridden) (\$\$)		6,000.00		
(\$\$)	19,163.07	6,000.00	13,163.07	68.69
+ GST 7.00/7.00% (\$\$)	1,341.41	420.00	921.41	68.69
Nett Amount (\$\$)	20,504.48	6,420.00	14,084.48	68.69

INSPECTION

Date of Assignment:	19/05/2022	
Date Inspected:	19/05/2022 Inspected At:	H S Automotives Pte Ltd (HQ) BLK 2 KAKI BUKIT AVENUE 2 #01-15 KAKI BUKIT AUOTHUB Singapore 417921
Estimated Period of Repair:	7.0 days	

Adjuster: Thevan Thomas Karthikesavan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Aug 2022)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB6062D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	938.41 F	*800.00 FL
2	1		*REAR BOOT LID OUTER GARNISH	Cut	395.41 F	*395.41 FL
3	1		*REAR BOOT LID LOGO (CAMRY)	Necessary	69.45 F	*69.45 FL
4	1		*REAR BOOT LID LOGO (2.5)	Necessary	66.30 F	*66.30 FL
5	1		*REAR BOOT LID CHROME (MOULDING)	Necessary	202.10 F	*202.10 FL
6	2		*REAR BOOT LID CHROME MOULDING L/R	Necessary	110.40 F	*110.40 FL
7	2		*REAR BOOT LID LAMP L/R	Cracked	790.80 F	*790.80 FL
8	2		*REAR BOOT LID N/PLATE LAMP L/R	Cracked	138.40 F	*138.40 FL
9	1		*REAR BOOT LID INNER TRIM	Serviceable	254.10 F	*- FL
10	1		*REAR BOOT LID INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
11	1		*REAR BOOT LID N/PLATE	Bent	50.00 FS	*40.00 FS
12	1		*REAR BOOT LID CAMERA	Serviceable	380.00 F	*- FL
13	2		*REAR BOOT LID HINGE L/R	Shifted	139.40 F	*139.40 FL
14	1		*REAR BOOT LID LOCK	Jammed	509.10 F	*300.00 FL
15	1		*REAR BOOT LID WEATHERSTRIP	Deformed	169.23 F	*169.23 FL
16	1		*REAR END PANEL	Dented	517.85 F	*517.85 FL
17	1		*REAR END PANEL TOP GARNISH	Cut	269.47 F	*269.47 FL
18	1		*REAR END PANEL GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
19	2		*REAR FENDER L/R	Repair	1,914.70 F	*- FL
20	2		*REAR FENDER TAIL LAMP L/R	Cracked	888.60 F	*759.40 FL
21	2		*REAR FENDER TAIL LAMP BRACKET (NPA)	Not Necessary	0.00 F	*- FL
22	1		*REAR BUMPER	Cut	691.30 F	*581.90 FL
23	1		*REARBUMPER REINFORCEMENT	Dented	397.55 F	*397.55 FL
24	2		*REAR BUMPER RETAINER L/R	Necessary	220.80 F	*220.80 FL
25	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	4		*REAR BUMPER REVERSE SENSOR	Cut	2,036.40 FS	*200.00 FS
27	2		*REAR BUMPER REFLECTOR	Cracked	220.80 F	*220.80 FL
28	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
29	1		*REAR SPARE TYRE PANEL	Repair	691.10 F	*- FL
30	1		*REAR SPARE TYRE TOP BOARD	Serviceable	479.35 F	*- FL
31	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	120.00 FS	*- FS
32	1		*REAR EXHAUST PIPE	Repair	1,028.40 F	*- FL
33	2		*REAR EXHAUST PIPE MOUNTING	Serviceable	134.60 F	*- FL
34	1		*REAR LOWER SKIRT	Cut	303.15 F	*253.00 FL
35	1		*REAR LOWER GARNISH 57628-06150	Cut	414.50 F	*414.50 FL
36	1		*REAR END PANEL ANTENNA 89997-33020	Jammed	201.40 F	*201.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,013.07	7,348.16
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,754.54
Total Parts (S\$)	15,013.07	5,593.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	1,800.00	1,200.00
2	SPRAY PAINT	New	1,600.00	1,200.00
3	CHECK WIRING	New	100.00	30.00
4	TO RUST PROOF	New	150.00	40.00
5	TO REMOVE / REFIX EXHAUST PIPE	New	200.00	70.00
6	TO INSTALL REVERSE SENSOR	New	120.00	40.00
7	TO REMOVE / REFIX WINDSCREEN	New	180.00	0.00
Gross Labour Cost (\$\$)			4,150.00	2,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >