

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004720/GVY3N2**Date:** 21/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00119582100
Claimant Vehicle No :	SNB7730D	Insured Vehicle No :	GBK6141E
Date of Loss:	09/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203224/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB7730D	Engine No:	LEB6731148
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU31311141
Reg. Date:	14/09/2021 (Man. Year: 2018)	Odometer:	43319 km
Colour:	Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,412.24	4,157.76	2,254.48	35.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,420.00	930.00	39.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,762.24	5,577.76	3,184.48	36.34
Approved Total (Overridden) (\$\$)		4,350.00		
(\$\$)	8,762.24	4,350.00	4,412.24	50.36
+ GST 7.00/7.00% (\$\$)	613.36	304.50	308.86	50.36
Nett Amount (\$\$)	9,375.60	4,654.50	4,721.10	50.36

INSPECTION

Date of Assignment:	19/05/2022	
Date Inspected:	24/05/2022	Inspected At: Vins Automotive Group (HQ) 160 SIN MING DRIVE #03-03 Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB7730D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,100.90 FL	*912.60 FL
2	1		*TAILGATE GLASS MOULDING	Necessary	96.30 FL	*96.30 FL
3	1		*TAILGATE VEZEL EMBLEM	Necessary	43.20 FL	*43.20 FL
4	1		*TAILGATE HYBRID EMBLEM	Necessary	70.50 FL	*70.50 FL
5	1		*TAILGATE REFLECTOR-RH	Cut	424.50 FL	*385.00 FL
6	1		*TAILGATE REFLECTOR-LH	Cut	424.50 FL	*385.00 FL
7	1		*TAILGATE RUBBER	Twisted	105.30 FL	*105.30 FL
8	1		*TAILGATE LOCK	Cut	256.10 FL	*180.00 FL
9	1		*TAILGATE WIPER MOTOR	Not Necessary	205.10 FL	*- FL
10	1		*TAILGATE INNER TRIMBOARD	Cut	153.40 FL	*153.40 FL
11	1		*TAILLAMP-RH	Cut	474.60 FL	*474.60 FL
12	1		*TAILLAMP-LH	Cut	474.60 FL	*474.60 FL
13	1		*REAR BUMPER	Deformed	829.60 FL	*829.60 FL
14	1		*REAR BUMPER RH REFLECTOR	Not Necessary	178.50 FL	*- FL
15	1		*REAR BUMPER LH REFLECTOR	Not Necessary	178.50 FL	*- FL
16	1		*REAR BUMPER SIDE RETAINER-RH	Not Necessary	17.50 FL	*- FL
17	1		*REAR BUMPER SIDE RETAINER-LH	Not Necessary	17.50 FL	*- FL
18	1		*REAR BUMPER ANTENNA SENSOR	Broken	80.10 FL	*80.10 FL
19	1		*REAR BUMPER BUZZLE SENSOR	Cracked	68.10 FL	*68.10 FL
20	10		*REAR BUMPER CLIPS	Necessary	42.00 FL	*42.00 FL
21	1		*REAR RH CORNER BUMPER	Not Necessary	172.80 FL	*- FL
22	1		*REAR LH CORNER BUMPER	Not Necessary	172.80 FL	*- FL
23	1		*REAR END PANEL	Repair	538.10 FL	*- FL
24	1		*REAR END PANEL TOP TRIM	Cut	98.20 FL	*98.20 FL
25	1		*SPARE TYRE PANEL TOP COVER	Deformed	459.60 FL	*245.00 FL
26	1		*SPARE TYRE PANEL COMPARTMENT BOX	Cracked	183.60 FL	*183.60 FL
27	1		*REAR FENDER INNER TRIMBOARD-RH	Broken	320.10 FL	*320.10 FL
28	1		*REAR FENDER INNER TRIMBOARD-LH	Not Necessary	320.10 FL	*- FL
29	1		*REAR RH WHEEL ARCH GARNISH	Not Necessary	192.10 FL	*- FL
30	1		*REAR LH WHEEL ARCH GARNISH	Not Necessary	192.10 FL	*- FL
31	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
32	1		*REAR WINDSCREEN GUM	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,990.30	5,187.20
- List Item Discount on L Items 20.00/20.00% (\$)	1,578.06	1,029.44
Total Parts (\$)	6,412.24	4,157.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
2	TO REPAIR DAMAGES	New	1,100.00	600.00
3	TO SPRAY PAINTING	New	1,100.00	700.00
Gross Labour Cost (S\$)			2,350.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >