

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004721/AVY3Q2**Date:** 25/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00096472104

**Claimant Vehicle
No :** SMP5070B**Insured Vehicle
No :** YP4011L

Date of Loss: 16/05/2022

Nature of Claim: TP

Claim
No: SNM22D203357/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMP5070B**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB7109878

Reg. Date: 27/09/2019 (Man. Year: 2019)

Chassis No: GP72007895

Colour: Black

Odometer: 104524 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R16

Rear Tyre Size:

205/45 R16

Front Left Side: Hankook 6 mm

Rear Left Side:

Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side:

Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,621.32	5,051.76	1,569.56	23.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	2,000.00	530.00	20.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,151.32	7,051.76	2,099.56	22.94
Approved Total (Overridden) (\$\$)		5,600.00		
(\$\$)	9,151.32	5,600.00	3,551.32	38.81
+ GST 7.00/7.00% (\$\$)	640.59	392.00	248.59	38.81
Nett Amount (\$\$)	9,791.91	5,992.00	3,799.91	38.81

INSPECTION

Date of Assignment: 19/05/2022

Date Inspected: 19/05/2022 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT
AUTOHUB
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Aug 2022)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP5070B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,350.60 FL	*958.00 FL
2	1		*REAR BUMPER REFLECTOR GARNISH L/R	N/S Cracked	90.00 FL	*45.00 FL
3	1		*REAR BUMPER REFLECTOR L/R	N/S Cracked	90.00 FL	*45.00 FL
4	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	53.00 FL	*53.00 FL
5	1		*REAR BUMPER SPONGE L/R	N/S Cracked	179.00 FL	*89.50 FL
6	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	16.50 FL	*- FL
7	1		*REAR BUMPER UNDER COVER LH	Not Necessary	98.30 FL	*- FL
8	1		*REAR BUMPER UNDER COVER RH	Not Necessary	95.20 FL	*- FL
9	1		*REAR END PANEL	Dented	560.80 FL	*560.80 FL
10	1		*REAR END PANEL INNER TOP GARNISH	Deformed	155.50 FL	*155.50 FL
11	1		*REAR TAILGATE	Deformed	1,193.00 FL	*1,193.00 FL
12	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.80 FL	*75.80 FL
13	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	38.00 FL	*- FL
14	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
15	2		*REAR TAILGATE HINGES L/R	Not Necessary	100.00 FL	*- FL
16	1		*REAR TAILGATE INNER PULL HANDLE	Not Necessary	25.00 FL	*- FL
17	2		*REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	Not Necessary	37.00 FL	*- FL
18	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	320.00 FL	*320.00 FL
19	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	27.50 FL	*- FL
20	1		*REAR TAILGATE MECHANISM LOCK	Damaged	157.10 FL	*157.10 FL
21	1		*REAR TAILGATE OUTER CHROME MOULDING WITH GARNISH	Not Necessary	383.10 FL	*- FL
22	1		*REAR TAILGATE OUTER LOCK OPENER SWITCH	Not Necessary	175.50 FL	*- FL
23	2		*REAR TAILGATE REFLECTOR INNER RUBBER GASKET L/R	Necessary	50.00 FL	*50.00 FL
24	2		*REAR TAILGATE REFLECTOR L/R	Cracked	790.00 FL	*790.00 FL
25	1		*REAR TAILGATE WEATHERSTRIP	Cut	168.50 FL	*168.50 FL
26	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
27	2		*REAR TAILLAMP L/R	Cracked	1,041.00 FL	*1,041.00 FL
28	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
29	1		*REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
30	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
31	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	40.00 FS	*30.00 FS
32	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
33	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
34	1		*SET REAR TAILGATE OUTER CHROME MOULDING WITH GARNISH CLIPS	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
36	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	30.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					8,110.40	6,227.20
- List Item Discount on L Items 20.00/20.00% (\$)					1,489.08	1,175.44
Total Parts (\$)					6,621.32	5,051.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (\$\$)			2,530.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >