

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004723/UGA3Q2**Date:** 10/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070150482
Claimant Vehicle No :	SKT8988L	Insured Vehicle No :	GBH9767X
Date of Loss:	18/05/2022	Nature of Claim:	TP
		Claim No:	0950639931SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT8988L	Engine No:	27294531942634
Make & Model:	MERCEDES-BENZ R300L, 3.0 (A)	Chassis No:	WDC2511542A139303
Reg. Date:	19/01/2012 (Man. Year: 2011)	Odometer:	244204 km
Colour:	Grey		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R18	Rear Tyre Size:	255/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,519.50	10,214.06	21,305.44	67.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,260.00	2,330.00	2,930.00	55.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,779.50	12,544.06	24,235.44	65.89
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	36,779.50	10,000.00	26,779.50	72.81
+ GST 7.00/7.00% (S\$)	2,574.57	700.00	1,874.57	72.81
Nett Amount (S\$)	39,354.07	10,700.00	28,654.07	72.81
+ Car Rental (7.0 x S\$180.00/day) (S\$)		1,260.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,962.00		

INSPECTION

Date of Assignment:	19/05/2022	
Date Inspected:	19/05/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,455.00 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	188.30 F	*188.30 FL
3	1		*TAILGATE	Dented / Bent	3,685.10 F	*3,115.20 FL
4	1		*TAILGATE OUTER CHROME HANLE	Bent	644.80 F	*590.50 FL
5	1		*TAILGATE REAR LOGO	Necessary	108.50 F	*75.00 FL
6	1		*TAILGATE R300 EMBLEM	Serviceable	145.00 F	*- FL
7	1		*TAILGATE C&C EMBLEM	Serviceable	50.00 F	*- FL
8	1		*TAILGATE 7G TRONIC EMBLEM	Serviceable	145.00 F	*- FL
9	1		*TAILGATE REAR WIPER ARM	Not Necessary	188.90 F	*- FL
10	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	620.00 F	*- FL
11	1		*TAILGATE WEATHERSTRIP	Not Necessary	388.90 F	*- FL
12	1		*TAILGATE INNER LOCK	Shorted / Damaged	841.90 F	*820.10 FL
13	1		*TAILGATE LOCK STRIKER	Not Necessary	60.00 F	*- FL
14	1		*TAILGATE INNER TRIM	Not Necessary	311.60 F	*- FL
15	1		*REAR BUMPER	Distorted	2,415.10 F	*2,162.30 FL
16	1		*REAR BUMPER LOWER GARNISH	Deformed / Warped	688.90 F	*580.00 FL
17	1		*REAR BUMPER TOP CHROME MOULDING	Cracked	820.00 F	*645.00 FL
18	2		*REAR BUMPER REFLECTORS	Cracked	170.00 F	*170.00 FL
19	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	330.00 F	*- FL
20	4		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	1,140.00 F	*430.00 FL
21	1		*REAR BUMPER UNDER COVER	Cracked	685.00 F	*520.00 FL
22	1		*REAR BUMPER BEAM	Serviceable	915.00 F	*- FL
23	1		*REAR BUMPER INNER PROTECTRO	Distorted	462.00 F	*382.00 FL
24	1		*REAR END PANEL OUTER	Dented / Bent	1,515.00 F	*1,415.00 FL
25	1		*REAR END PANEL LOCK SENSOR	Not Necessary	350.00 F	*- FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	368.90 F	*- FL
27	2		*TAILLAMPS	Not Necessary	1,701.00 F	*- FL
28	2		*TAILLAMP HOUSING PANELS	Not Necessary	900.60 F	*- FL
29	1		*REAR FENDER	Not Necessary	2,205.10 F	*- FL
30	2		*REAR FENDER INNER TRIM BOARDS	Not Necessary	1,370.20 F	*- FL
31	1		*REAR FLOOR PANEL	Not Necessary	1,415.10 F	*- FL
32	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	622.30 F	*- FL
33	1		*REAR FLOOR PANEL TOP TRAY	Not Necessary	588.10 F	*- FL
34	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	520.80 F	*- FL
35	1		*REAR EXHAUST	Not Necessary	1,885.10 F	*- FL
36	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	188.30 F	*- FL
37	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
38	1		*SET REAR BUMPER UNDER COVER CLIPS	Necessary	50.00 FS	*50.00 FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
40	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
41	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
42	1		*SET TAILGATE INNER TRIM INSULATOR	Not Necessary	300.00 FS	*- FS
43	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	450.00 FS	*- FS
44	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **31,519.50** **11,323.40**
- List Item Discount on L Items 0.00/10.00% (\$\$) **0.00** **1,109.34**

Total Parts (\$\$) **31,519.50** **10,214.06**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR FENDER GLASS	New	100.00	0.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
8	TO SPRAY PROOFING	New	180.00	60.00
9	TO DIAGNOSTIC & REPROGRAMME SYSTEM	New	380.00	50.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,000.00	800.00
11	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,080.00
Gross Labour Cost (\$\$)			5,260.00	2,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >