

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004725/UPA3Q2**Date:** 03/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800085215
Claimant Vehicle No :	SKC3016P	Insured Vehicle No :	SMA6862E
Date of Loss:	18/05/2022	Nature of Claim:	TP
		Claim No:	2697563685SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC3016P		
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Engine No:	G4FGBU283598
Reg. Date:	11/08/2011 (Man. Year: 2011)	Chassis No:	KMHDH41CMCU221453
Colour:	Grey	Odometer:	116413 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,968.00	11,174.64	13,793.36	55.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	3,870.00	2,380.00	38.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,218.00	15,044.64	16,173.36	51.81
Approved Total (Overridden) (S\$)		12,000.00		
(S\$)	31,218.00	12,000.00	19,218.00	61.56
+ GST 7.00/7.00% (S\$)	2,185.26	840.00	1,345.26	61.56
Nett Amount (S\$)	33,403.26	12,840.00	20,563.26	61.56
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,442.00		
Global Sum Settlement (S\$)		13,400.00		

INSPECTION

Date of Assignment:	19/05/2022	
Date Inspected:	19/05/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,966.20 F	*1,782.00 FL
2	1		*BOOTLID H LOGO	Necessary	39.90 F	*39.90 FL
3	1		*BOOTLID HYUNDAI EMBLEM	Necessary	48.50 F	*48.50 FL
4	1		*BOOTLID ELANTRA EMBLEM	Necessary	45.00 F	*45.00 FL
5	1		*BOOTLID S EMBLEM	Not fitted	45.00 F	*- FL
6	2		*BOOTLID REFLECTORS	Cracked	900.00 F	*850.00 FL
7	1		*BOOTLID INNER LOCK	Bent	188.90 F	*188.90 FL
8	1		*BOOTLID INNER TRIM	Deformed / Torn	322.50 F	*292.30 FL
9	2		*BOOTLID HINGES	Bent / Twisted	300.00 F	*300.00 FL
10	1		*BOOTLID WEATHERSTRIP	Twisted	299.20 F	*139.20 FL
11	1		*REAR BUMPER	Distorted	845.20 F	*498.00 FL
12	2		*REAR BUMPER REFLECTORS	Cracked	210.00 F	*136.00 FL
13	1		*REAR BUMPER SPONGE	Not fitted	188.00 F	*- FL
14	1		*REAR BUMPER BEAM	Cracked	516.80 F	*341.00 FL
15	2		*REAR BUMPER BEAM BRACKETS	Bent	310.00 F	*310.00 FL
16	1		*REAR BUMPER LOWER GARNISH	Not fitted	299.00 F	*- FL
17	2		*REAR BUMPER SIDE RETAINERS	Bent	130.00 F	*130.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
19	2		*TAILLAMPS	Cracked	1,370.00 F	*1,197.20 FL
20	2		*TAILLAMP HOUSING PANELS	Bent	510.00 F	*490.00 FL
21	1		*REAR END PANEL	Badly Dented	785.20 F	*585.90 FL
22	1		*REAR END PANEL BUZZLE SENSOR	Not fitted	250.00 F	*- FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	199.00 F	*199.00 FL
24	1		*REAR FLOOR PANEL	Crumpled / Buckled	1,280.00 F	*981.50 FL
25	1		*REAR FLOOR PANEL TOP BOARD	Warped	615.00 F	*398.80 FL
26	1		*REAR EXHAUST	Repair	688.10 F	*- FL
27	1		*REAR EXHAUST HEAT SHIELD	Bent	152.80 F	*126.50 FL
28	1		*REAR FENDER	Repair	1,907.00 F	*- FL
29	2		*REAR FENDER INNER TRIMS	Deformed / Torn	798.00 F	*622.00 FL
30	1		*REAR WINDSCREEN MOULDING	Not Necessary	86.00 F	*- FL
31	1		*BONNET	Repair	1,361.20 F	*- FL
32	1		*BONNET LOCK	Not Necessary	145.00 F	*- FL
33	1		*FRONT BUMPER	Deformed / Torn	699.20 F	*485.00 FL
34	2		*FRONT BUMPER SIDE RETAINERS	Bent	90.00 F	*90.00 FL
35	1		*FRONT BUMPER LOWER CENTRE GRILLE	Serviceable	98.50 F	*- FL
36	1		*FRONT BUMPER SPONGE	Torn	244.10 F	*182.00 FL
37	1		*FRONT BUMPER BEAM	Repair	451.00 F	*- FL
38	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
39	1		*FRONT GRILLE	Cracked	421.60 F	*305.60 FL
40	1		*FRONT GRILLE LOGO	Necessary	60.00 F	*38.00 FL
41	2		*HEADLAMPS	Holder Cracked	2,396.00 F	*2,396.00 FL
42	1		*FRONT SUPPORT PANEL	Repair	866.10 F	*- FL
43	1		*AIR CON CONDENSER	Not Necessary	980.00 F	*- FL
44	1		*RADIATOR	Not Necessary	1,055.00 F	*- FL
45	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
46	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
47	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	200.00 FS	*180.00 FS
48	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
49	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
50	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
51	1		*FRONT LICENCE PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,968.00	13,833.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	2,658.66

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	24,968.00
						11,174.64
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	0.00
7	TO DISMANTLE & REFIX PETROL TANK	New	100.00	60.00
8	TO SPRAY RUST PROOFING	New	100.00	80.00
9	TO RESET & REPROGRAMME SYSTEM	New	180.00	50.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,800.00	1,600.00
11	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,800.00
Gross Labour Cost (\$\$)			6,250.00	3,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >