



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 9899E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEFORMED	1,881.00	1,881.00
1	FRT BUMPER RETAINER LH	NOT NECESSARY	126.00	-
2	FRT PARKING SENSORS	DAMAGED (1 PCS ONLY)	660.00	280.00
1	FRT BUMPER AIR GRILLE	CUT	113.00	113.00
1	FRT FOG LAMP COVER LH	NOT NECESSARY	155.00	-
1	FRT FENDER PROTECTOR LH	CUT	206.00	206.00
1	FRT BUMPER LOWER CHROME	NOT NECESSARY	129.00	-
1	HEADLAMP LH	CUT	3,494.00	3,494.00
	LESS 10% DISCOUNT		-676.40	-597.40
			6,087.60	5,376.60
1	FRT RIM LH (SN)	CUT	2,477.00	1,600.00
	LESS 10% DISCOUNT		-247.70	-
			2,229.30	1,600.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRT TYRE LH (SN)	NOT NECESSARY	400.00	-
			400.00	-
	<u>LABOUR</u>			
	TO CHECK WIRING .		100.00	30.00
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO DIAGNOSE AND PROGRAM.		450.00	180.00
	(FRONT) TO SPRAY PAINTING.		700.00	250.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS.		700.00	350.00
			2,100.00	890.00
	GRAND TOTAL		10,816.90	7,866.60

Report Ref No. CS/SMO22004727/Avy3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,300.00
---	--	--	-----------------

Report Ref No. CS/SMO22004727/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.