

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004729/BVY3Q2**Date:** 09/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00260332100
Claimant Vehicle No :	GBC5490X	Insured Vehicle No :	SGE7272B
Date of Loss:	16/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203321/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC5490X	Engine No:	1KDFTV
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (M)	Chassis No:	JTFAT35Y30K202161
Reg. Date:	(Man. Year: 1900)	Odometer:	220960 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/70 R15	Rear Tyre Size:	155 R12C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,297.00	4,008.00	10,289.00	71.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	1,580.00	3,500.00	68.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,377.00	5,588.00	13,789.00	71.16
Approved Total (Overridden) (S\$)		4,450.00		
(S\$)	19,377.00	4,450.00	14,927.00	77.03
+ GST 8.00/8.00% (S\$)	1,550.16	356.00	1,194.16	77.03
Nett Amount (S\$)	20,927.16	4,806.00	16,121.16	77.03

INSPECTION

Date of Assignment:	08/02/2023	
Date Inspected:	20/05/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Feb 2023)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC5490X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	651.00 FL	*651.00 FL
2	1		*FRONT BUMPER LH BRACKET	Bent	212.00 FL	*121.00 FL
3	1		*FRONT GRILLE	Broken	567.00 FL	*567.00 FL
4	1		*FRONT GRILLE EMBLEM	Necessary	75.00 FL	*75.00 FL
5	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FL	*30.00 FL
6	1		*LH HEADLAMP ASSY	Cut	978.00 FL	*978.00 FL
7	1		*SET LH HEADLAMP LOCK CLIPS	Necessary	32.00 FL	*20.00 FL
8	1		*FRONT PANEL	Not Damaged	1,019.00 FL	*- FL
9	1		*FRONT PANEL DYNA EMBLEM	Not Necessary	93.00 FL	*- FL
10	1		*FRONT LH CORNER PANEL	Dented	442.00 FL	*264.00 FL
11	1		*FRONT LH CORNER PANEL UPPER GARNISH	Not Necessary	193.00 FL	*- FL
12	1		*SET FRONT LH CORNER PANEL UPPER GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
13	1		*LH SIDE MIRROR ARM	Not Damaged	683.00 FL	*- FL
14	1		*LH SIDE ROUND MIRROR	Not Damaged	189.00 FL	*- FL
15	1		*LH SIDE RECTANGLE MIRROR	Not Damaged	412.00 FL	*- FL
16	1		*LH FRONT DOOR	Dented	1,776.00 FL	*1,485.00 FL
17	1		*LH FRONT DOOR UPPER HINGE	Not Damaged	116.00 FL	*- FL
18	1		*LH FRONT DOOR LOWER HINGE	Bent	116.00 FL	*116.00 FL
19	1		*LH FRONT DOOR CHECKER	Not Damaged	132.00 FL	*- FL
20	1		*LH FRONT DOOR INNER TRIM BOARD	Broken	551.00 FL	*551.00 FL
21	1		*SET LH FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	50.00 FL	*30.00 FL
22	1		*LH FRONT DOOR GLASS REGULATOR GEAR	Bent	376.00 FL	*376.00 FL
23	1		*LH FRONT DOOR GLASS REGULATOR GEAR MOTOR	Not Damaged	448.00 FL	*- FL
24	1		*LH FRONT DOOR LOCK	Not Damaged	354.00 FL	*- FL
25	1		*LH FRONT DOOR PILLAR	Not Damaged	876.00 FL	*- FL
26	1		*LH FRONT DOOR PILLAR RUBBER SEAL	Not Damaged	281.00 FL	*- FL
27	1		*LH FRONT DOOR QUARTER GARNISH	Not Damaged	113.00 FL	*- FL
28	1		*LH FRONT DOOR SPEAKER	Not Damaged	221.00 FL	*- FL
29	1		*LH FRONT DOOR WEATHERSTRIP	Not Damaged	363.00 FL	*- FL
30	1		*LH FRONT DOOR LOWER RUBBER SEAL	Not Damaged	94.00 FL	*- FL
31	1		*LH FRONT STEP GARNISH	Not Damaged	312.00 FL	*- FL
32	1		*LH FRONT STEP GARNISH PANEL	Not Damaged	274.00 FL	*- FL
33	1		*LH FRONT ARCH PANEL	Not Damaged	391.00 FL	*- FL
34	1		*LH FRONT ARCH PANEL GARNISH	Not Damaged	287.00 FL	*- FL
35	1		*SET LH FRONT ARCH PANEL GARNISH CLIPS	Not Damaged	35.00 FL	*- FL
36	1		*DASHBOARD	Not Damaged	972.00 FL	*- FL
37	1		*LH FRONT LOWER ARM	Not Damaged	1,029.00 FL	*- FL
38	1		*LH FRONT LOWER ARM BALL JOINT	Not Damaged	562.00 FL	*- FL
39	1		*LH FRONT SHOCK ABSORBER	Not Damaged	364.00 FL	*- FL
40	1		*LH FRONT KNUCKLE ARM	Not Damaged	1,248.00 FL	*- FL
41	1		*LH FRONT WHEEL BEARING	Not Damaged	312.00 FL	*- FL
42	1		*LH FRONT MUDGUARD	Not Damaged	317.00 FL	*- FL
43	1		*LH FRONT DOOR COMPANY DETAIL STICKER	Necessary	40.00 FS	*20.00 FS
44	1		*LH FRONT DOOR PILLAR SEAL	Not Necessary	70.00 FS	*- FS
45	1		*FRONT NUMBER PLATE	Bent	70.00 FS	*40.00 FS
46	1		*LH FRONT RIM	Not Necessary	550.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*LH FRONT TYRE	Not Necessary	300.00 FS	*- FS
48	1		*BRAKE FLUID	Not Necessary	70.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	18,696.00	5,324.00
				- List Item Discount on L Items 25.00/25.00% (S\$)	4,399.00	1,316.00
				Total Parts (S\$)	14,297.00	4,008.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,800.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,500.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	0.00
5	REMOVE AND REINSTALL DASHBOARD AND ALL DASHBOARD ATTACHMENTS TO CARRY REPAIR	New	300.00	0.00
6	REFOCUS AND ADJUST HEADLAMPS ASSY	New	80.00	0.00
7	REMOVE AND REPLACE FRONT LH DOOR INNER MECHANISM TO CARRY REPAIR	New	120.00	80.00
8	REMOVE AND REINSTALL AIRCON BLOWER AND HEATER TO CARRY REPAIR .TO REFILL GAS	New	320.00	0.00
9	REMOVE ,REINSTALL AND REPLACE FRONT LH INNER TRIMS ,GARNISH AND SEAT TO CARRY REPAIR	New	280.00	0.00
10	ADJUST AND TEST DRIVE WHEEL ALIGNMENT	New	100.00	0.00
11	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	380.00	0.00
Gross Labour Cost (S\$)			5,080.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >