



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 293K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT GRILLE (N)	SCRATCHED	916.00	916.00
1	FRONT GRILLE LOGO (N)	SERVICEABLE	180.00	-
1	FRONT HEADLAMP (N)	CRACKED	2,200.00	1,050.00
1	FRONT SUPPORT PANEL (N)	BROKEN	2,160.00	475.00
1	FRONT BUMPER (N)	DENTED	1,983.00	990.00
1	FRONT BUMPER REINFORCEMENT (N)	DENTED	1,895.00	850.00
1	DAST POT (N)	SCRATCHED	201.00	201.00
	LESS 10% DISCOUNT		-953.50	-448.20
			8,581.50	4,033.80
	<b><u>LABOUR</u></b>			
	TO REMOVE AND REFIT FRONT HEADLAMPS WIRING.		50.00	30.00
	TO REMOVE AND REFIT AIR-CON CONDENSOR.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT RADIATOR.	NOT NECESSARY	120.00	-
	TO REMOVE, REFIT AND REPAIR ALL THE ABOVE PARTS.		1,000.00	400.00
	TO SPRAY PAINT ON THE REPLACEMENT AND REPAIR PARTS.		800.00	400.00
			2,150.00	830.00
	<b>GRAND TOTAL</b>		<b>10,731.50</b>	<b>4,863.80</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,900.00</b>
<b>LESS EXCESS</b>			<b>-2,000.00</b>
<b>NETT LIABILITY</b>			<b>1,900.00</b>

Report Ref No. CS/FCI22004730/Vny3m4

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.