

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22004733/KQY3E2

Date: 30/06/2022

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SMR2757M **Insured Vehicle No :** SMM6635G
Date of Loss: 17/05/2022 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR2757M**
Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: A25A0530100
Reg. Date: 27/12/2019 (Man. Year: 2019) Chassis No: MR2B63HK304004074
Colour: Metallic Black Odometer: 47837 km
Engine Capacity: 2487 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,595.08	16,555.42	7,039.66	29.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,260.00	2,650.00	2,610.00	49.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,855.08	19,205.42	9,649.66	33.44
+ GST 7.00/7.00% (S\$)	2,019.86	1,344.38	675.48	33.44
Nett Amount (S\$)	30,874.94	20,549.80	10,325.14	33.44

INSPECTION

Date of Assignment: 19/05/2022
Date Inspected: 20/05/2022 Inspected At: Sin Ming Autocare BFG Pte Ltd (HQ)
176, Sin Ming Drive #02-05, Sin Ming Autocare Complex
Singapore 575721
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$19,205.43

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2022)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR2757M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,576.90 FL	*1,572.80 FL
2	1		*BOOT HINGE RH	Repair	228.00 FL	*- FL
3	1		*BOOT HINGE LH	Repair	228.00 FL	*- FL
4	1		*BOOT LIDE HINGE COVER LH	Serviceable	85.60 FL	*- FL
5	1		*BOOT LIDE HINGE COVER RH	Serviceable	85.60 FL	*- FL
6	1		*BOOT LID WEATHERSTRIP	Distorted / Dented	284.70 FL	*284.70 FL
7	1		*BOOT LOCK	Repair	423.90 FL	*- FL
8	1		*BOOT OUTER MOULDING	Serviceable	245.10 FL	*- FL
9	1		*BOOT EMBLEM LOGO	Necessary	85.60 FL	*85.60 FL
10	1		*BOOT EMBLEM CAMRY	Not Necessary	108.15 FL	*- FL
11	1		*BOOT EMBLEM 2.5	Necessary	77.10 FL	*77.10 FL
12	1		*BOOT INNER TRIM	Serviceable	795.50 FL	*- FL
13	20		*BOOT INNER TRIM CLIP	Not Necessary	90.00 FL	*- FL
14	1		*TAIL LAMP RH	Cut	914.25 FL	*908.30 FL
15	1		*TAIL LAMP LH	Cut	914.25 FL	*908.30 FL
16	1		*TAIL LAMP PANEL RH	Repair	282.70 FL	*- FL
17	1		*TAIL LAMP PANEL LH	Repair	282.70 FL	*- FL
18	1		*SPARE WHEEL PANEL	Repair	996.90 FL	*- FL
19	1		*SPARE WHEEL PANEL COVER	Dented	589.80 FL	*589.80 FL
20	1		*REAR BODY PANEL	Bent	896.61 FL	*892.35 FL
21	1		*REAR BODY PANEL TOP GARNISH	Mtg Distorted	334.20 FL	*334.20 FL
22	1		*REAR FENDER INNER TRIM LH	Serviceable	481.60 FL	*- FL
23	1		*REAR FENDER INNER TRIM RH	Serviceable	481.60 FL	*- FL
24	1		*REAR BUMPER	Bent	678.80 FL	*678.80 FL
25	1		*REAR BUMPER BRACKET	Repair	85.60 FL	*- FL
26	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	131.80 FL	*- FL
27	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	131.80 FL	*- FL
28	1		*REAR EXHAUST MUFFLER	Repair	1,073.80 FL	*- FL
29	1		*REAR TAIL LAMP SIDE COVER LH	Serviceable	75.10 FL	*- FL
30	1		*REAR TAIL LAMP SIDE COVER RH	Serviceable	75.10 FL	*- FL
31	1		*REAR BUMPER REFLECTOR RH	Serviceable	86.50 FL	*- FL
32	1		*REAR BUMPER REFLECTOR LH	Serviceable	86.50 FL	*- FL
33	1		*REAR BUMPER LOWER GARNISH	Buckled	542.10 FL	*542.10 FL
34	1		*REAR BAZER SENSOR	Serviceable	198.50 FL	*- FL
35	1		*REAR REVERSE SENSOR WIRE	Serviceable	385.10 FL	*- FL
36	1		*REAR TOOL BOX	Serviceable	198.70 FL	*- FL
37	1		*REAR TOOL BOX TRAY	Dented	482.49 FL	*482.49 FL
38	1		*REAR BUMPER REINFORCEMENT	Bent	382.20 FL	*382.20 FL
39	1		*FRONT BUMPER	Buckled	838.40 FL	*801.40 FL
40	1		*FRONT BUMPER CENTER GRILLE	Cracked	760.50 FL	*760.50 FL
41	1		*FRONT BUMPER TOP RUBBER	Necessary	117.15 FL	*117.15 FL
42	1		*FRONT BUMPER CENTER GRILLE BASE	Cracked	245.15 FL	*245.15 FL
43	1		*FRONT GRILLE	Cracked	450.10 FL	*450.10 FL
44	1		*FRONT GRILLE LOGO	Cut	1,091.60 FL	*1,072.20 FL
45	1		*FRONT HEADLAMP RH	Mtg Cracked	4,635.90 FL	*4,614.80 FL
46	1		*FRONT HEADLAMP LH	Mtg Cracked	4,635.90 FL	*4,614.80 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	248.20 FL	*- FL
48	1		*TOWING COVER	Serviceable	38.15 FL	*- FL
49	1		*FRONT NUMBER PLATE }	Dented	50.00 FS	*45.00 FS
50	1		*FRONT NUMBER PLATE HOLDER }		30.00 FS	*- FS
51	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
52	1		*REAR NUMBER PLATE HOLDER	Serviceable	30.00 FS	*- FS
53	1		*REAR REVERSE SENSOR CENTER RH	Shorted	392.80 F	*361.80 FN
54	1		*REAR REVERSE SENSOR CENTER LH	Serviceable	392.80 FS	*- FS
55	1		*REAR CAMERA	Serviceable	480.00 FS	*- FS
56	1		*FRONT BUMPER SPONGE	Serviceable	158.15 FL	*- FL
57	1		*FRONT RADIATOR SIDE GARNISH RH	Distorted	109.20 FL	*109.20 FL
58	1		*FRONT RADIATOR SIDE GARNISH LH	Cracked	109.20 FL	*109.20 FL
59	1		*FRONT BUMPER NUMBER BASE	Cracked	124.80 FL	*124.80 FL
60	1		*REAR COMPARTMENT LOWER COVER	Cracked	894.06 FL	*894.06 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	30,984.91	22,058.90
- List Item Discount on L Items 25.00/25.00% (S\$)	7,389.83	5,413.03
- Nett Item Discount on N Items 0.00/25.00% (S\$)	0.00	90.45
Total Parts (S\$)	23,595.08	16,555.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT ON AFFECTED AREAS	New	2,500.00	800.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON EFFECTED	New	1,800.00	1,500.00
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL	New	200.00	60.00
4	LABOUR TO REMOVE AND REPLACE REAR BOOTLID	New	200.00	50.00
5	TO CHECK WIRING FUNCTIONS	New	80.00	40.00
6	OBN DIAGNOSTIC	New	480.00	200.00
Gross Labour Cost (S\$)			5,260.00	2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >