



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 9332S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	822.30	822.30
1	REAR BUMPER SIDE RETAINER	CRACKED	62.40	62.40
1	REAR CONCAVE BUMPER LH	DEFORMED	320.00	320.00
1	REAR FENDER LH	NOT NECESSARY	1,855.30	-
	LESS 25% DISCOUNT		-765.00	-301.18
			2,295.00	903.52
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	REFLECTOR CHROME (SN)	CUT	180.00	100.00
			200.00	120.00
	<u>LABOUR</u>			
	TO PANEL BEAT, REMOVE AND REPLACE PARTS.		1,000.00	200.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	500.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
			2,450.00	750.00
	GRAND TOTAL		4,945.00	1,773.52
	RECOMMENDED COST OF REPAIRS			1,773.52

Report Ref No. CS/AGI22004735/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.