

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 7600A

| Qty | Description of Parts  | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS  |                         |                               |                   |
| 1   | FRONT FENDER  | TO REPAIR SEE<br>LABOUR | 79.00                         | -                 |
| 1   | PAIR FRAME SLIDER   | O/S CUT                 | 360.00                        | 180.00            |
| 1   | L/H FRONT SIGNAL LIGHT  | NOT AFFECTED            | 95.00                         | -                 |
| 1   | R/H FRONT SIGNAL LIGHT  | SCRATCHED               | 95.00                         | 95.00             |
| 1   | L/H CLUTCH CONTROL LEVER  | NOT NECESSARY           | 49.00                         | -                 |
| 1   | R/H BRAKE CONTROL LEVER   | SCRATCHED               | 49.00                         | 49.00             |
| 1   | HEAVY BALANCER  | SCRATCHED               | 85.00                         | 75.00             |
| 1   | SIDE MIRROR   | SCRATCHED               | 198.00                        | 152.00            |
| 1   | R/H SHROUD  | DAMAGED                 | 174.00                        | 174.00            |
| 1   | PAIR RIDER FOOTREST   | O/S CUT                 | 190.00                        | 75.00             |
| 1   | BRAKE FOOT PEDAL  | BENT                    | 85.00                         | 85.00             |
| 1   | SILVER BRACKET  | SERVICEABLE             | 95.00                         | -                 |
| 1   | L/H REAR SIGNAL LIGHT   | NOT NECESSARY           | 95.00                         | -                 |
| 1   | R/H REAR SIGNAL LIGHT   | DAMAGED                 | 95.00                         | 95.00             |
| 1   | COVER LICENCE LIGHT   | SCRATCHED               | 95.00                         | 70.00             |
|     | LESS 10% DISCOUNT   |                         | -                             | -105.00           |
|     |   |                         | 1,839.00                      | 945.00            |
|     | SPECIAL NETT ITEMS  |                         |                               |                   |
| 1   | SEAT CUSHION (LOCAL REPAIR) (SN)  | SCRATCHED               | 500.00                        | 280.00            |
| 1   | REAR METAL BOX (SN)   | DAMAGED                 | 580.00                        | 500.00            |
| 1   | REAR NUMBER PLATE (SN)  | BENT                    | 35.00                         | 25.00             |
| 1   | ROLL REFLECTIVE STICKER (SN)  | NOT NECESSARY           | 45.00                         | -                 |
|     |   |                         | 1,160.00                      | 805.00            |
|     | <u>LABOUR</u>   |                         |                               |                   |
|     | TO DISMANTLE AND REPAIR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER. |                         | 700.00                        | 300.00            |
|     | TO CHECK WIRING.  |                         | 60.00                         | 20.00             |

Report Ref No. CS3/GAI22000779/Vvy3e2-1



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,800.00

| Qty | Description of Parts                        | Condition | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-----------|-------------------------------|-------------------|
|     | TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS. |           | 350.00                        | 150.00            |
|     |   |           | 1,110.00                      | 470.00            |
|     | GRAND TOTAL                                 |           | 4,109.00                      | 2,220.00          |

Report Ref No. CS3/GAI22000779/Vvy3e2-1

**RECOMMENDED COST OF LUMP SUM REPAIRS** 

(TO ITS PRE-ACCIDENT CONDITION)

P

THEVAN THOMAS KARTHIKESAVAN

**Asst. Automotive Assessor** 

P

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**